

# Aervoe Crown 6004 Kleer Kote

INGREDIENTS	CAS NO	%	8HR OEL
n-butyl acetate	123-86-4	10-30	713 mg/m3
acetone	67-64-1	30-60	1185 mg/m3
propylene glycol monomethyl ether acetate, alpha-isomer	108-65-6	1-5	274 mg/m3
hydrocarbon propellant	68476-85-7.	10-30	1800 mg/m3



UN No: 1950 Hazchem Code: 2YE DG Class: 2.1

Subsidiary Risk: Not Applicable Packing Group: Not Applicable Poisons Schedule: Not Applicable



# NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

### **HEALTH HAZARD INFORMATION**













**Acute Health** Effects: Irritating to eyes, respiratory system and skin. Vapours may cause drowsiness and dizziness.

Chronic **Health Effects:**  Repeated exposure may cause skin dryness and cracking.

\* - limited evidence

# PRECAUTIONS FOR USE













Glasses:	Consider chemical goggles.
Gloves:	1.PE/EVAL/PE 2.BUTYL/NEOPRENE
Respirator:	Type AX Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)
Storage and Transportation:	Store in cool, dry, protected area. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep container in a well ventilated place. Keep away from heat. Keep away from sources of ignition. No smoking.
Fire/Explosion Hazard:	HIGHLY FLAMMABLE. Vapours/gas heavier than air. Toxic smoke/fumes in a fire. Risk of explosion if heated under confinement. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at

BREATHE FUMES.

hazardous or special waste collection point. In case of fire and/or explosion, DO NOT

#### **PROPERTIES**











Liquid.

Gas.

Does not mix with water.

Floats on water. Extremely flammable.

### **EMERGENCY**



#### **FIRST AID**

Swallowed:	Contact Doctor or Poisons Centre.  Do NOT give milk or oil.  Do NOT give alcohol.
Skin:	Wash with soap & water. Apply cleansing cream.
Advice To Doctor:	No antidote. Supportive care. Evaluate for respiratory distress. Consider lavage with cuffed tube. NO adrenalin.

Keep containers cool. Fire Fighting: Water spray/ fog.

> Eliminate ignition sources. Prevent from entering drains. Contain spillage by any means.

Absorb with dry agent. Stop leak if safe to do so. Use only in well ventilated areas.

Spills and Disposal:

Take precautionary measures against static

discharges.

Dispose of this material and its container at hazardous or special waste collection point.

This material and its container must be disposed of

in a safe way.

To clean the floor and all objects contaminated by this material, use water and detergent.

### SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS











Explosive Toxic Radioactive Oxidizing x x x x

- Must not be stored together