

Hempel'S Curing Agent 97371

INGREDIENTS	CAS NO	%	8HR OEL
XYLENE	1330-20-7	10-23	350 mg/m3
isobutanol	78-83-1	5-10	152 mg/m3
ethylbenzene	100-41-4	3-5	434 mg/m3
diethylaminotrimethyleneamine	104-78-9	10-16	-



UN No: 2733 Hazchem Code: •2W DG Class: 3 Subsidiary Risk: 8 Packing Group: III Poisons Schedule: \$5

HEALTH HAZARD INFORMATION



NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

PROPERTIES





Liquid, Corrosive, Alkaline, Flammable,









Harmful by inhalation. Harmful in contact with skin. Harmful if swallowed. Causes burns. Risk of serious damage to eyes.

May cause SENSITISATION by inhalation. May cause SENSITISATION by skin contact. Vapours may cause drowsiness and dizziness.

Chronic **Health Effects:**

Acute Health

Effects:

Limited evidence of a carcinogenic effect.

* - limited evidence

FIRST AID

Swallowed:	Give water (if conscious). URGENT MEDICAL ATTENTION. Do NOT give milk or oil. Do NOT give
	alcohol.
Eye:	Wash with running water (15 mins). Medical attention.
Skin:	Flood body with water. Remove contaminated clothing. Wash with water
Inhaled:	Fresh air. Rest, keep warm. If breathing shallow, give oxygen. Medical attention.
Advice To Doctor:	Supportive care. Irrigate eyes with saline. Supportive care. Evaluate for respiratory distress. Consider lavage with cuffed tube. NO adrenalin.

Fire Fighting:

Spills and

Disposal:

Water spray/ fog. Foam - alcohol type.

Eliminate ignition sources. Prevent from entering drains. Contain spillage by any means. Absorb with dry agent. Stop leak if safe to do so. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all

objects contaminated by this material, use water and detergent.

PRECAUTIONS FOR USE





Appropriate

engineering

controls:







Local Exhaust Ventilation recommended.



Glasses: Consider chemical goggles. 1.VITON 2.PE/EVAL/PE 3.PVA Gloves: Type AK-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 Respirator: or national equivalent) Restrictions on Storage apply. Refer to Full Report. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special Storage and waste collection point. Keep locked up. Keep out of Transportation: reach of children. Keep away from living quarters.

Fire/Explosion Hazard: Flammable. Toxic smoke/fumes in a fire. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point.

Keep away from food, drink and animal feeding

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS













+ X X X X

Flammable Explosive Toxic Radioactive Oxidizing Harmful



Must not be stored together