

# Schlumberger Non-Emulsifying Agent W54

INGREDIENTS	CAS NO	%	8HR OEL
methanol	67-56-1	30-60	262 mg/m3
naphthalene	91-20-3	<1	52 mg/m3
alcohols C9-11-iso-, C10-rich, ethoxylated	78330-20-8	5-10	-
alcohols C11-14-iso-, C13-rich, ethoxylated	78330-21-9	1-5	-



LIN No: 1992 Hazchem Code: •3WE DG Class: 3 Subsidiary Risk: 6.1 Packing Group: II Poisons Schedule: S6

## NFPA Rating:

- ▶ 0: Minimum
- ▶1: Low
- ▶ 2: Moderate
- **▶3:** High
- ▶ 4: Extreme







HEALTH HAZARD INFORMATION





**Acute Health** 

Toxic by inhalation. Toxic in contact with skin. Toxic if swallowed. Irritating to skin.

Toxic: Danger of very serious irreversible effects through inhalation, in contact with skin and if swallowed. Risk of serious damage to eyes

**Chronic Health** Effects:

Limited evidence of a carcinogenic effect.

\*- limited evidence

# PRECAUTIONS FOR USE













∠DX	
$\mathcal{H}$	

### Appropriate engineering controls:

Local Exhaust Ventilation recommended

Glasses:

Consider chemical goggles.

Gloves:

1.PE/EVAL/PE 2.PVDC/PE/PVDC

Respirator:

Type AX-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)


Storage and Transportation:

Restrictions on Storage apply. Refer to Full Report. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. Keep locked up. Keep out of reach of children. Keep away from living guarters. Keep container in a well ventilated place. Keep away from food, drink and animal feeding stuffs. Keep away from sources of ignition. No smoking.

Fire/Explosion Hazard: HIGHLY FLAMMABLE. Toxic smoke/fumes in a fire. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. In case of fire and/or explosion, DO NOT BREATHE FUMES.







### **EMERGENCY**

**PROPERTIES** 













# FIRST AID

Swallowed:

If more than 15 mins from Doctor, INDUCE VOMITING (if conscious). Eye: Wash with running water (15 mins). Medical attention.

Skin:

Wipe-off with clean/dry cloth. Remove contaminated clothing. Wash with water & soap. MEDICAL ATTENTION.

Inhaled:

Fresh air. Rest, keep warm. If breath shallow, give oxygen. Medical

Advice To Doctor:

Decontaminate with ipecac or lavage. Ethanol therapy.

Fire Fighting:

Spills and

Disposal:

Keep containers cool. Water spray/ fog. Foam - alcohol type. Eliminate ignition sources. Consider evacuation. Prevent from entering

drains. Contain spillage by any means. Control vapour with water spray/ fog. Absorb with dry agent. Stop leak if safe to do so. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material, use

# SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS









Х



Flammable Explosive Х

х

Toxic Radioactive Oxidizing

Must not be stored together