

# 3M Scotch-Weld EC-1300 L TF Contact Rubber Adhesive

INGREDIENTS	CAS NO	%	8HR OEL
METHYL ETHYL KETONE	78-93-3	15-30	445 mg/m3
n-propyl acetate	109-60-4	7-13	835 mg/m3
MAGNESIUM OXIDE	1309-48-4.	1-5	10 mg/m3
ZINC AND ZINC OXIDE	1314-13-2	0.1-1	10 mg/m3



UN No: 1133 Hazchem Code: •3YE

DG Class: 3

Subsidiary Risk: Not Applicable

Packing Group: II

Poisons Schedule: Not Applicable

## NFPA Rating:

- ▶ 0: Minimum
- **1:** Low
- ▶ 2: Moderate
- **▶ 3:** High
- ▶ 4: Extreme

### **HEALTH HAZARD INFORMATION**















Irritating to eyes

Irritating to respiratory system.

**Acute Health** Effects:

**Chronic Health** 

Effects:

Irritating to skin. May cause SENSITISATION by skin contact.

HARMFUL-May cause lung damage if swallowed.

Vapours may cause drowsiness and dizziness.

Possible risk of irreversible effects

Harmful: danger of serious damage to health by prolonged

exposure through inhalation.

Possible risk of impaired fertility.

Possible risk of harm to the unborn child.

Repeated exposure may cause skin dryness and cracking.

– limited evidence

#### PRECAUTIONS FOR USE













-	
	Appropriate
	engineering
	controls

Local Exhaust Ventilation recommended

Glasses:

Consider chemical goggles.

Gloves:

1.PE/EVAL/PE 2.PVA 3.TEFLON

Respirator:

Type AX-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

Storage and Transportation: Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep container in a well ventilated place. Keep away from food, drink and animal feeding stuffs. Keep away from sources of ignition. No smoking.

Fire/Explosion Hazard: HIGHLY FLAMMABLE. Toxic smoke/fumes in a fire. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. In case of fire and/or explosion, DO NOT BREATHE **FUMES** 

# **PROPERTIES**







Liquid.Highly flammable.

#### **EMERGENCY**









### **FIRST AID**

Swallowed:

Skin:

Inhaled:

Spills and

Disposal:

Give water (if conscious). Seek medical advice. Do NOT give milk

or oil. Do NOT give alcohol.

Eye: Wash with running water.

Flood body with water. Remove contaminated clothing. Wash with

Fresh air. Rest, keep warm. If breath shallow, give oxygen.

Medical attention

Advice To Doctor:

Evaluate for respiratory distress. Consider lavage with cuffed tube.

NO adrenalin.

Fire Fighting: Keep containers cool. Foam.

> Spilled liquid has low boiling temperature and evaporates quickly. Eliminate ignition sources. Prevent from entering drains. Contain

spillage by any means. Control vapour with water spray/ fog. Absorb with dry agent. Stop leak if safe to do so. Take precautionary measures against static discharges. Dispose of this

material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe

way. To clean the floor and all objects contaminated by this material, use water and detergent.

# SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS





х



Х



Explosive Х

Toxic

Radioactive Oxidizing

x — Must not be stored together