

## Henkel Turco Dy-Chek Developer Step 4 Aerosol

| INGREDIENTS            | CAS NO      | %      | 8HR OEL    |
|------------------------|-------------|--------|------------|
| isopropanol            | 67-63-0     | >60    | 983 mg/m3  |
| hydrocarbon propellant | 68476-85-7. | 10-30  | 1800 mg/m3 |
| silica amorphous       | 7631-86-9   | 0-4.99 | 10 mg/m3   |
| aluminium oxide        | 1344-28-1   | 0-9.99 | 10 mg/m3   |



UN No: 1950 Hazchem Code: 2YE DG Class: 2.1

Subsidiary Risk: Not Applicable Packing Group: Not Applicable Poisons Schedule: Not Applicable



#### NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

## **HEALTH HAZARD INFORMATION**





**Acute Health** Effects: Irritating to eyes.

Vapours may cause drowsiness and dizziness.

## PRECAUTIONS FOR USE













| Glasses:                       | Consider chemical goggles.   |
|--------------------------------|--|
| Gloves:                        | 1.NITRILE, PVC 2.PE/EVAL/PE  |
| Respirator:                    | Type AX Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent) |
| Storage and<br>Transportation: | Store in cool, dry, protected area.  |

Fire/Explosion

HIGHLY FLAMMABLE.

Hazard:

Vapours/gas heavier than air. Toxic smoke/fumes in a fire.

## **PROPERTIES**







Gas.

Mixes with water. Extremely flammable.

#### **EMERGENCY**



## **FIRST AID**

| Skin:                | Wash with soap & water. Apply cleansing cream.   |
|----------------------|--|
| Advice To<br>Doctor: | Evaluate for respiratory distress. Consider lavage with cuffed tube. NO adrenalin.       |
| Fire Fighting:       | Keep containers cool.<br>Water spray/ fog.<br>Foam - alcohol type.                       |
| Spills and Disposal: | Eliminate ignition sources. Prevent from entering drains. Contain spillage by any means. |

# SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS









Explosive

Toxic

Radioactive Oxidizing

x x Х

- Must not be stored together