

## Hempel Hempadur Multi-Strength GF 35879

INGREDIENTS	CAS NO	%	8HR OEL
xylene	1330-20-7	5-10	350 mg/m3
ethylbenzene	100-41-4	1-3	434 mg/m3
bisphenol A/ diglycidyl ether resin, liquid	25068-38-6	35-50	-
n-butanol	71-36-3	3-5	-



UN No: 1263 Hazchem Code: •3Y DG Class: 3

Subsidiary Risk: None Packing Group: III Poisons Schedule: \$5



### NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

### **HEALTH HAZARD INFORMATION**









**Acute Health** Effects: Harmful by inhalation. Irritating to eyes. Irritating to skin.

May cause SENSITISATION by skin contact.

Chronic **Health Effects:**  Limited evidence of a carcinogenic effect.

\* - limited evidence

## PRECAUTIONS FOR USE

















# **Appropriate** engineering

Local Exhaust Ventilation recommended.

controls: Glasses:

Consider chemical goggles.

Gloves:

1.PE/EVAL/PE 2.PVA 3.VITON

Type A-P Filter of sufficient capacity. (AS/NZS

Respirator:

1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

Storage and Transportation:

Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep away from food, drink and animal feeding stuffs.

Fire/Explosion Hazard: Flammable. Toxic smoke/fumes in a fire. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point.

### **PROPERTIES**



Liquid Flammable.

#### **EMERGENCY**









### **FIRST AID**

Give water (if conscious). URGENT MEDICAL Swallowed: ATTENTION.

Eye: Wash with running water.

Remove contaminated clothing. Wash with soap & Skin:

Fresh air. Rest, keep warm. If breathing shallow, Inhaled:

give oxygen. Medical attention.

**Advice To** Doctor:

Treat symptomatically.

Fire Fighting:

Spills and

Disposal:

Foam.

Eliminate ignition sources. Prevent from entering drains. Contain spillage by any means. Absorb with dry agent. Stop leak if safe to do so. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all

objects contaminated by this material, use water

and detergent.

## SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS









Explosive

Toxic х

Radioactive Oxidizing Х

- Must not be stored together