

PPG PS 700 Part A

INGREDIENTS	CAS NO	%	8HR OEL
methyl ethyl ketone	78-93-3	15-40	445 mg/m3
isopropanol	67-63-0	30-60	983 mg/m3
hexamethylenetetramine/ ethyl chloride copolymer	63512-71-0	10-30	-



UN No: 1133 Hazchem Code: •3YE DG Class: 3

Subsidiary Risk: Not Applicable

Packing Group: II Poisons Schedule: \$5



NFPA Rating:

- ▶ 0: Minimum
- ▶ 2: Moderate
- **▶ 3:** High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION











Irritating to eyes. Irritating to skin.

Vapours may cause drowsiness and dizziness.

Chronic **Health Effects:** Repeated exposure may cause skin dryness and cracking

* – limited evidence

PRECAUTIONS FOR USE















Appropriate engineering controls:

Local Exhaust Ventilation recommended.

Glasses:

Consider chemical goggles.

Gloves:

1.TEFLON 2.PE/EVAL/PE 3.PVA

Respirator:

Type AK-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

Storage and Transportation:

Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep container in a well ventilated place. Keep away from sources of ignition. No smoking.

Fire/Explosion Hazard:

HIGHLY FLAMMABLE. Toxic smoke/fumes in a fire. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. In case of fire and/or explosion, DO NOT BREATHE FUMES.

PROPERTIES









Liquid. Does not mix with water. Floats on water. Highly flammable.

EMERGENCY





Skin:







FIRST AID

Swallowed:	Give water (if conscious). Seek medical advice.
Eye:	Wash with running water (15 mins). Medical attention.
Cleim.	Remove contaminated clothing. Wash with soap &

Fresh air. Rest, keep warm. If breathing shallow, Inhaled:

give oxygen. Medical attention.

Severe exposure indicated by respiratory Advice To distress/hypotension Managements is essentially Doctor:

supportive.

Fire Fighting: Keep containers cool. Foam.

> Spilled liquid has low boiling temperature and evaporates quickly. Eliminate ignition sources. Consider evacuation. Prevent from entering drains. Contain spillage by any means. Control vapour with water spray/ fog. Absorb with dry agent. Stop leak if safe to do so. Use only in well ventilated areas. Take precautionary measures against static

discharges. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material, use water

and detergent.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS





Spills and

Disposal:





Radioactive Oxidizing

x x x x Must not be stored together