

AIRCRAFT PAINT PRIMER ZINC CHROMATE PRIMER

INGREDIENTS	CAS NO	%	8HR OEL
toluene	108-88-3	10-30	191 mg/m3
xylene	1330-20-7	10-30	350 mg/m3
heptane	31394-54-4	5-10	1640 mg/m3
zinc chromate	13530-65-9	10-30	0.05 mg/m3



UN No: 1263 Hazchem Code: •3YE DG Class: 3

Subsidiary Risk: Not Applicable

Packing Group: II

Poisons Schedule: Paint1 S6



NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION



















Harmful by inhalation, in contact with skin and if swallowed.

Acute Health Irritating to eyes and skin.

May cause SENSITISATION by skin contact. Effects:

HARMFUL-May cause lung damage if swallowed. Vapours may cause drowsiness and dizziness.

May cause CANCER.

Harmful: danger of serious damage to health by prolonged exposure through inhalation.

Chronic **Health Effects:** Possible risk of harm to the unborn child.

* - limited evidence

PRECAUTIONS FOR USE





Environment:









Glasses: Consider chemical goggles. Gloves: 1.VITON 2.PVA 3.NITRILE, PVC

Type A Filter of sufficient capacity. (AS/NZS 1716 Respirator: & 1715, EN 143:2000 & 149:2001, ANSI Z88 or

national equivalent)

Storage and Store in cool, dry, protected area.

Transportation: Restrictions on Storage apply. Refer to Full Report.

HIGHLY FLAMMABLE. Fire/Explosion Vapours/gas heavier than air. Hazard: Toxic smoke/fumes in a fire.

Very toxic to aquatic organisms.

May cause long-term adverse effects in the aquatic environment. Use appropriate container to

avoid environmental contamination.

Avoid release to the environment. Refer to special instructions/Safety data sheets.

PROPERTIES









Does not mix with water. Sinks in water. Highly flammable.

EMERGENCY









FIRST AID

Contact Doctor or Poisons Centre. Swallowed: Give glass of water.

Eye: Wash with running water.

Wash with soap & water. Apply cleansing cream. Skin:

Fresh air. Rest, keep warm. If breathing shallow, Inhaled:

give oxygen. Medical attention.

Advice To Evaluate for respiratory distress. Consider lavage Doctor: with cuffed tube. NO adrenalin.

Keep containers cool.

Fire Fighting: Foam.

Eliminate ignition sources. Consider evacuation.

Prevent from entering drains.

Spills and Contain spillage by any means. Disposal:

Control vapour with water spray/ fog. Absorb with dry agent.

Stop leak if safe to do so.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS











Flammable Explosive x x x x

- Must not be stored together