

Betz Dearborn Steamate NA4220

INGREDIENTS	CAS NO	%	8HR OEL
cyclohexylamine	108-91-8	1-10	41 mg/m3
diethylaminoethanol	100-37-8	1-10	48 mg/m3
morpholine	110-91-8	1-10	71 mg/m3
water	7732-18-5	>60	-



UN No: 2734 Hazchem Code: •2W DG Class: 8 Subsidiary Risk: 3 Packing Group: II

Poisons Schedule: Not Applicable

NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

PROPERTIES







Liquid. Mixes with water. Corrosive.

Alkaline. Highly flammable.

HEALTH HAZARD INFORMATION









Acute Health Effects: Harmful in contact with skin and if swallowed.

Causes burns.

Risk of serious damage to eyes.

Chronic **Health Effects:** Possible risk of impaired fertility.

* – limited evidence

PRECAUTIONS FOR USE















Appropriate engineering controls:

Local Exhaust Ventilation recommended.

Glasses:

Consider chemical goggles.

Gloves:

1.BUTYL 2.PVA

Respirator:

Type AEK-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

Restrictions on Storage apply. Refer to Full Report.

Keep locked up.

Keep out of reach of children.

Storage and

Keep away from living quarters.

Keep container in a well ventilated place. Transportation: Keep away from food, drink and animal feeding

Keep away from sources of ignition. No smoking.

Fire/Explosion Hazard: HIGHLY FLAMMABLE. Vapours/gas heavier than air.

Toxic smoke/fumes in a fire. In case of fire and/or explosion, DO NOT

BREATHE FUMES.



EMERGENCY







FIRST AID

Swallowed:	Contact Doctor or Poisons Centre. Give glass of water.
Eye:	Wash with running water (15 mins). Medica attention.

Flood body with water. Remove contaminated Skin: clothing. Wash with water

Fresh air. Rest, keep warm. If breathing shallow, Inhaled:

give oxygen. Medical attention.

Supportive care. Irrigate eyes with saline.

Advice To Supportive care.

Assist ventilation Hypotension - Trendelenburg Doctor:

Position. Methylene blue for severe poisoning.

Keep containers cool.

Fire Fighting: Water spray/ fog.

> Eliminate ignition sources. Prevent from entering drains. Contain spillage by any means.

Spills and Disposal: Absorb with dry agent. Stop leak if safe to do so.

This material and its container must be disposed of

in a safe way.

To clean the floor and all objects contaminated by

this material, use water.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS











Toxic Radioactive Oxidizing Explosive х х x