

The Sherwin-Williams 981300 Series-Jet Flex Urethane White BAC 70913

INGREDIENTS	CAS NO	%	8HR OEL
cyclohexanone	108-94-1	<10	100 mg/m3
n-butyl acetate	123-86-4	10-25	713 mg/m3
propylene glycol monomethyl ether acetate, alpha-isomer	108-65-6	<5	274 mg/m3
Toluene (Reference Fuel)	108-88-3	<5	191 mg/m3



UN No: 1263 Hazchem Code: •3YE DG Class: 3

Subsidiary Risk: Not Applicable

Packing Group: II

Poisons Schedule: Not Applicable

NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- **▶3:** High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION











Irritating to eyes

Vapours may cause drowsiness and dizziness

Harmful: danger of serious damage to health by prolonged exposure

through inhalation.

Chronic Health Effects:

May cause CANCER by inhalation. Possible risk of harm to the unborn child.

Repeated exposure may cause skin dryness and cracking.

*- limited evidence

PRECAUTIONS FOR USE













Appropriate engineering controls:

Local Exhaust Ventilation recommended

Glasses:

Consider chemical goggles. 1.VITON/CHLOROBUTYL 2.VITON

Gloves:

Respirator:

Type A Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent) Store in cool, dry, protected area. Restrictions on Storage apply. Refer

Storage and Transportation:

to Full Report. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep container in a well ventilated place. Keep away from sources of ignition.

Fire/Explosion

Hazard:

HIGHLY FLAMMABLE. Vapours/gas heavier than air. Toxic smoke/fumes in a fire. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. In case of fire and/or explosion, DO NOT BREATHE FUMES.

Environment:

May cause long-term adverse effects in the aquatic environment. May cause long-term adverse effects in the environment. Use appropriate container to avoid environmental contamination. Avoid release to the environment. Refer to special instructions/Safety data sheets.

PROPERTIES





Liquid.Highly flammable.

EMERGENCY











FIRST AID

Swallowed:

Give water (if conscious). Seek medical advice. Do NOT give milk or oil. Do NOT give alcohol.

Eye: Wash with running water. Skin:

Remove contaminated clothing. Wash with soap & water. Fresh air. Rest, keep warm. If breath shallow, give oxygen. Medical

Inhaled:

Treat symptomatically. Evaluate for respiratory distress. Consider

Advice To Doctor:

Spills and

Disposal:

lavage with cuffed tube. NO adrenalin. Assist ventilation Hypotension -Trendelenburg Position. Methylene blue for severe poisoning.

Fire Fighting: Keep containers cool. Foam.

Eliminate ignition sources. Consider evacuation. Pollutant. Prevent

from entering drains. Contain spillage by any means. Control vapour with water spray/ fog. Absorb with dry agent. Stop leak if safe to do so. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material, use

water and detergent.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS











Toxic х

х Must not be stored together