

# 3M Scotchkote Brand Electrical Coating

INGREDIENTS	CAS NO	%	8HR OEL
toluene	108-88-3	10-15	191 mg/m3
methyl ethyl ketone	78-93-3	10-15	445 mg/m3
acetone	67-64-1	40-45	1185 mg/m3
octylated diphenylamines	68411-46-1	0.1-1	2 mg/m3



UN No: 1866 Hazchem Code: •3YE DG Class: 3

Subsidiary Risk: Not Applicable

Packing Group: II Poisons Schedule: \$5



#### NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

### **HEALTH HAZARD INFORMATION**

















Irritating to eyes. May cause SENSITISATION by skin contact. HARMFUL-May cause lung damage if swallowed. Vapours may cause drowsiness and dizziness.

Chronic **Health Effects:**  Limited evidence of a carcinogenic effect. Harmful: danger of serious damage to health by prolonged exposure through inhalation. Possible risk of harm to the unborn child. Repeated exposure may cause skin dryness and cracking.

\* - limited evidence

# PRECAUTIONS FOR USE















### **Appropriate** engineering controls:

Local Exhaust Ventilation recommended.

Glasses: Consider chemical goggles.

Gloves:

1.PVDC/PE/PVDC 2.VITON 3.PVA

Respirator:

Type AX Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

Storage and Transportation:

Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep container in a well ventilated place. Keep away from food, drink and animal feeding stuffs. Keep away from sources of ignition. No smoking.

Fire/Explosion Hazard:

HIGHLY FLAMMABLE. Toxic smoke/fumes in a fire. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. In case of fire and/or explosion, DO NOT BREATHE FUMES.

#### **PROPERTIES**





Liquid. Highly flammable.









RST	• A I	
וכאו	A	ı

Swallowed: Give water (if conscious). Seek medical advice. Wash with running water (15 mins). Medical

Wipe-off with clean/dry cloth. Remove Skin: contaminated clothing. Wash with water & soap.

MEDICAL ATTENTION.

Fresh air. Rest, keep warm. If breathing shallow, Inhaled:

give oxygen. Medical attention.

Advice To Doctor:

Eye:

No antidote. Supportive care.

Fire Fighting: Keep containers cool. Foam.

Spilled liquid has low boiling temperature and evaporates quickly. Eliminate ignition sources. Consider evacuation. Prevent from entering drains. Contain spillage by any means. Control vapour with water spray/ fog. Absorb with dry agent. Stop leak if safe to do so. Take precautionary measures against static discharges. Dispose of this material and its

Spills and Disposal:

container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material, use water

and detergent.

## SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS









Explosive

Toxic Х

Radioactive Oxidizing

х х

- Must not be stored together