

Amercoat 4151

INGREDIENTS	CAS NO	%	8HR OEL
diethylenetriamine	111-40-0	10-30	4.2 mg/m3
isobutanol	78-83-1	<5	152 mg/m3
4,4'-methylenebis(2-ethylaniline)	19900-65-3	30-60	-
n-butanol	71-36-3	10-30	-



UN No: 2920 Hazchem Code: •3W DG Class: 8 Subsidiary Risk: 3 Packing Group: II

Poisons Schedule: Not Applicable



NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

PROPERTIES





Liquid, Corrosive, Alkaline, Flammable,









HEALTH HAZARD INFORMATION















Harmful by inhalation. Harmful in contact with skin.

Harmful if swallowed. Causes severe burns.

Risk of serious damage to eyes.

May cause SENSITISATION by skin contact. Vapours may cause drowsiness and dizziness.

Chronic **Health Effects:**

Acute Health

Effects:

Limited evidence of a carcinogenic effect.

* - limited evidence

PRECAUTIONS FOR USE

















Appropriate engineering controls:

Local Exhaust Ventilation recommended.

Glasses:

Consider full face-shield.

Gloves:

1.HYPALON 2.PE/EVAL/PE 3.PVA

Respirator:

Storage and

Transportation:

Type AK-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

Restrictions on Storage apply. Refer to Full Report. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. Keep locked up. Keep out of reach of children. Keep away from living quarters. Keep away from food, drink and animal feeding

stuffs.

Fire/Explosion Hazard:

HIGHLY FLAMMABLE. Vapours/gas heavier than air. Toxic smoke/fumes in a fire. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point.

FIRST AID

Give water (if conscious). URGENT MEDICAL Swallowed: ATTENTION. Do NOT give milk or oil. Do NOT give alcohol. Wash with running water (15 mins). Medical Eye: attention.

Skin:

Flood body with water. Remove contaminated

clothing. Wash with water

Inhaled:

Fresh air. Rest, keep warm. If breath shallow, give

oxygen. Medical attention.

Supportive care. Irrigate eyes with saline.

Advice To Doctor:

Supportive care. Assist ventilation Hypotension -Trendelenburg Position. Methylene blue for severe

poisoning.

Fire Fighting:

Keep containers cool. Foam.

entering drains. Contain spillage by any means.

Spills and Disposal:

Absorb with dry agent. Stop leak if safe to do so. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material, use water and detergent.

Eliminate ignition sources. Pollutant. Prevent from

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS









Explosive

Toxic x x

Х

Radioactive Oxidizing

- Must not be stored together