

# **Hempel Paints Hempadur 85671**

INGREDIENTS	CAS NO	%	8HR OEL
XYLENE	1330-20-7	10-15	350 mg/m3
isobutanol	78-83-1	2-5	152 mg/m3
ethylbenzene	100-41-4	2-5	434 mg/m3
bisphenol F/ epichlorohydrin copolymer	9003-36-5	20-30	-



UN No: 1263 Hazchem Code: •3Y DG Class: 3 Subsidiary Risk: None

Packing Group: III Poisons Schedule: \$5



## NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

# **HEALTH HAZARD INFORMATION**















**Acute Health** Effects: Harmful by inhalation.

Harmful in contact with skin.

Irritating to skin.

Risk of serious damage to eyes.

May cause SENSITISATION by skin contact. Vapours may cause drowsiness and dizziness.

Chronic **Health Effects:**  Limited evidence of a carcinogenic effect.

\* - limited evidence

# PRECAUTIONS FOR USE















# **Appropriate** engineering controls:

Local Exhaust Ventilation recommended.

Glasses:

Consider chemical goggles.

Gloves:

1.VITON 2.PE/EVAL/PE 3.PVA

Respirator:

Type A Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or

national equivalent)

Storage and Transportation:

Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep away from food, drink and animal feeding stuffs.

Fire/Explosion Hazard:

Flammable. Toxic smoke/fumes in a fire. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point.

## **PROPERTIES**





Liquid.Flammable.







#### **FIRST AID**

Swallowed:

Rinse mouth with water.

Eye:

Wash with running water. For discomfort seek

medical advice.

Skin: Wash with soap

Inhaled:

Fresh air. Rest, keep warm.

Advice To

Spills and

Disposal:

Doctor:

Treat symptomatically.

Fire Fighting:

Foam.

Eliminate ignition sources. Prevent from entering drains. Contain spillage by any means. Absorb with dry agent. Stop leak if safe to do so. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material, use water

and detergent.

# SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS









Explosive

X

Toxic Radioactive Oxidizing X X

- Must not be stored together