

UOP HYT-1118 Q1.3 UOP Hydrotreating Catalyst

INGREDIENTS	CAS NO	%	8HR OEL
MOLYBDENUM (VI) OXIDE	1313-27-5	<25	10 mg/m3
SILICA AMPHOROUS	7631-86-9	<10	10 mg/m3
cobalt (II) oxide	1307-96-6	<9	-
ALUMINA H152, H155	1344-28-1.	<85	10 mg/m3



UN No: 3077 Hazchem Code: 2Z DG Class: 9

Subsidiary Risk: Not Applicable

Packing Group: III

Poisons Schedule: Not Applicable

NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION











Acute Health Effects: Irritating to eyes.

Irritating to respiratory system.

May cause SENSITISATION by skin contact.

Danger of cumulative effects. Limited evidence of a carcinogenic effect. Harmful: danger of serious damage to health by prolonged exposure through inhalation and if

swallowed.

* - limited evidence

Health Effects:

Chronic





Appropriate

PRECAUTIONS FOR USE









engineering controls:	Local Exhaust Ventilation recommended.
Glasses:	Consider full face-shield.
Gloves:	PVC chemical resistant type.
Respirator:	Particulate. (AS/NZS 1716 & 1715, EN 143:2000 & 149:001, ANSI Z88 or national equivalent)
Storage and Transportation:	Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children.
Fire/Explosion Hazard:	Dispose of this material and its container at hazardous or special waste collection point.

PROPERTIES







Solid. Does not mix with water. Sinks in water. Does not burn.

EMERGENCY











FIRST AID

Swallowed:	If more than 15 mins from Doctor, INDUCE VOMITING (if conscious).
Eye:	Wash with running water (15 mins). Medical attention.
Skin:	Flood body with water. Remove contaminated clothing. Wash with water
Inhaled:	Fresh air. Rest, keep warm. If breath shallow, give oxygen. Medical attention.
Advice To Doctor:	Deferoxamine is preferred chelator. Supportive care. "metal fume fever". Remove from exposure. Treatment is supportive.
Fire Fighting:	Keep containers cool. Keep surrounding area cool. Water spray/fog.
Spills and Disposal:	Pollutant. Avoid dust. Prevent from entering drains. Contain spillage by any means. Sweep shovel to safe place. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material, use water and detergent.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS





Explosive Radioactive

x x

- Must not be stored together