



Basic Tree Risk Assessment Form

Client Field test 6 Date 04/08/2026 Time 11:59
 Address/Tree location Windward Ln, Rancho Cordova, CA 95670 Tree no. 1 Sheet 1 of 1
 Tree species Liquidambar styraciflua dbh 25" Height 60' Crown spread dia. 34'
 Assessor(s) Roger Erismann Time frame three-year assessment Tools used smartphone, binoculars, measuring tape

Target Assessment

Target number	Target description	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
		Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
<u>1</u>	<u>Home</u>		<u>X</u>		<u>3</u>		
<u>2</u>	<u>Sidewalk</u>		<u>X</u>		<u>2</u>		
<u>3</u>							
<u>4</u>							

Site Factors

History of failures No history of failures Topography Flat ☒ Slope ☐ % Aspect _____
 Site changes None ☒ Grade change ☐ Site clearing ☐ Changed soil hydrology ☐ Root cuts ☐ Describe Suburban green space
 Soil conditions Limited volume ☐ Saturated ☐ Shallow ☐ Compacted ☐ Pavement over roots ☐ % Describe Soil conditions are good
 Prevailing wind direction W Common weather Strong winds ☒ Ice ☐ Snow ☐ Heavy rain ☒ Describe Strong winds, heavy rain

Tree Health and Species Profile

Vigor Low ☐ Normal ☐ High ☒ Foliage None (seasonal) ☐ None (dead) ☐ Normal 100 % Chlorotic 0 % Necrotic 0 %
 Pests No pests observed Abiotic A little bit of evidence of string trimmers and mowers over roots
 Species failure profile Branches ☒ Trunk ☐ Roots ☒ Describe Tendency to form V-shaped unions, included bark, overextended branches

Load Factors

Wind exposure Protected ☐ Partial ☒ Full ☐ Wind funneling ☐ Relative crown size Small ☒ Medium ☐ Large ☐
 Crown density Sparse ☐ Normal ☒ Dense ☐ Interior branches Few ☐ Normal ☒ Dense ☐ Vines/Mistletoe/Moss ☐ No vines/mistletoe/moss observed
 Recent or planned change in load factors none noted

Tree Defects and Conditions Affecting the Likelihood of Failure

— Crown and Branches —

Unbalanced crown ☐ LCR 80 %
 Dead twigs/branches ☐ 0 % overall Max. dia. _____
 Broken/Hangers Number 0 Max. dia. _____
 Over-extended branches ☐
 Pruning history
 Crown cleaned ☒ Thinned ☐ Raised ☐
 Reduced ☒ Topped ☐ Lion-tailed ☐
 Flush cuts ☐ Other professionally maintained
 Cracks ☐ Lightning damage ☐
 Codominant ☐ none evident Included bark ☐
 Weak attachments ☐ Cavity/Nest hole _____ % circ.
 Previous branch failures ☐ Similar branches present ☐
 Dead/Missing bark ☒ Cankers/Galls/Burls ☐ Sapwood damage/decay ☐
 Conks ☐ Heartwood decay ☐
 Response growth _____
 Main concern(s) We are unaware of previous branch failures.

Load on defect N/A ☒ Minor ☐ Moderate ☐ Significant ☐ n/a
 Likelihood of failure Improbable ☒ Possible ☐ Probable ☐ Imminent ☐ improbable

— Trunk —

Dead/Missing bark ☐ Abnormal bark texture/color ☐
 Codominant stems ☐ Included bark ☐ Cracks ☐
 Sapwood damage/decay ☐ Cankers/Galls/Burls ☐ Sap ooze ☐
 Lightning damage ☐ Heartwood decay ☐ Conks/Mushrooms ☐
 Cavity/Nest hole _____ % circ. Depth _____ Poor taper ☐
 Lean _____ ° Corrected? _____
 Response growth _____
 Main concern(s) There are no concerns for the trunk.

Load on defect N/A ☒ Minor ☐ Moderate ☐ Significant ☐
 Likelihood of failure
 Improbable ☒ Possible ☐ Probable ☐ Imminent ☐

— Roots and Root Collar —

Collar buried/Not visible ☐ Depth _____ Stem girdling ☐
 Dead ☐ Decay ☐ Conks/Mushrooms ☐
 Ooze ☐ Cavity ☐ _____ % circ.
 Cracks ☐ Cut/Damaged roots ☒ Distance from trunk _____
 Root plate lifting ☐ Soil weakness ☐
 Response growth _____
 Main concern(s) There really are no concerns here

Load on defect N/A ☒ Minor ☐ Moderate ☐ Significant ☐
 Likelihood of failure
 Improbable ☒ Possible ☐ Probable ☐ Imminent ☐

