Insured: Jason A

Property: 110 N CHESTNUT ST

WOODLAND, NC 27897

Estimator: Office Business: (704) 678-2783

Claim Number: PR02105351 Policy Number: Type of Loss: Water Damage

Date of Loss: Date Received:


Date Inspected: Date Entered: 6/26/2025 4:55 PM

Price List: NCEC8X\_JUN25

Restoration/Service/Remodel

Estimate: 110-N-CHESTNUT-ST

### 110-N-CHESTNUT-ST Main Level



139.78 SF Walls 164.28 SF Walls & Ceiling

**Bathroom** 

2.72 SY Flooring19.83 LF Ceil. Perimeter

Height: 8'
24.50 SF Ceiling

24.50 SF Floor

17.00 LF Floor Perimeter

Missing	Wall	- Goes	to 1	Floor
7411991115	vv an	- Gues	W I	LIOUL

#### 2' 10" X 6' 8"


#### Opens into SHOWER

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Walls							
1. Tear out wet drywall, cleanup, bag for disposal	37.33 SF	1.12	0.35	8.44	50.60	(0.00)	50.60
Tear out wet drywall on the wall where	vanity was in b	athroom, see pics to	confirm dama	ge.			
2. Clean stud wall	37.33 SF	1.01	0.05	7.56	45.31	(0.00)	45.31
3. HEPA Vacuuming - Detailed - (PER SF	) 37.33 SF	0.79	0.00	5.90	35.39	(0.00)	35.39
Hepa vacuuming is necessary to kill any	bacterial and n	nold growth after se	vere water dan	nage.			
4. 1/2" drywall - hung, taped, ready for texture	37.33 SF	2.46	1.94	18.74	112.51	(0.00)	112.51
5. Texture drywall - heavy hand texture	37.33 SF	1.46	0.66	11.04	66.20	(0.00)	66.20
6. Seal/prime (1 coat) then paint (1 coat) the surface area	37.33 SF	1.13	0.58	8.56	51.32	(0.00)	51.32
Paint newly replaced drywall.							
7. Tear out wet paneling, bag for disposal	102.44 SF	0.70	0.55	14.46	86.72	(0.00)	86.72
Tearing out water damaged paneling on	side walls of bo	uth.					
8. Apply anti-microbial agent to the surface area	102.44 SF	0.32	0.35	6.64	39.77	(0.00)	39.77
Necessary to kill any bacterial growth af	ter water dama	ge.					
9. Paneling	102.44 SF	2.90	5.88	60.60	363.56	(0.00)	363.56
10. Seal & paint paneling	102.44 SF	1.40	1.80	29.04	174.26	(0.00)	174.26
Painting the newly replaced paneling.							
11. Paint the walls - one coat	139.78 SF	0.78	1.60	22.12	132.75	(0.00)	132.75
Paint whole bath to match.							
12. Remove Stud wall - 2" x 4" x 8' - 16" oc	5.50 LF	2.21	0.00	2.44	14.60	(0.00)	14.60

The wall in between the bath and shower is to be removed to make the shower area wider.

#### **CONTINUED - Bathroom**

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Flooring							
13. Tear out subfloor & bag for disposal	24.50 SF	2.11	0.12	10.36	62.18	(0.00)	62.18
Removing the damaged subfloor in the b	ath.						
14. HEPA Vacuuming exposed framing - Floor - (PER SF)	24.50 SF	1.27	0.00	6.22	37.34	(0.00)	37.34
15. Underlayment - 5/8" OSB	24.50 SF	2.13	1.82	10.80	64.81	(0.00)	64.81
16. Tile floor covering	28.18 SF	14.58	10.44	84.26	505.56	(0.00)	505.56
Floor tiles with added wastage.							
17. Grout sealer	24.50 SF	1.85	0.31	9.12	54.76	(0.00)	54.76
18. Baseboard - 3 1/4"	17.00 LF	4.17	2.28	14.64	87.81	(0.00)	87.81
19. Seal (1 coat) & paint (2 coats) baseboard	17.00 LF	2.52	0.25	8.62	51.71	(0.00)	51.71
Plumbing & Miscellaneous							
20. Vanity - Reset	3.50 LF	38.37	0.00	26.86	161.16	(0.00)	161.16
21. Sink - single - Reset	1.00 EA	102.73	0.05	20.56	123.34	(0.00)	123.34
22. Sink faucet - Detach & reset	0.50 EA	136.35	0.00	13.64	81.82	(0.00)	81.82
23. Rough-in plumbing - per fixture	1.00 EA	759.85	11.20	154.22	925.27	(0.00)	925.27
Plumbing to be done for vanity, includes	supply lines and	all.					
24. Detach & Reset Light bar - 6 lights	1.00 EA	116.32	0.00	23.26	139.58	(0.00)	139.58
Final Cleaning							
25. Final cleaning - construction - Residential	24.50 SF	0.34	0.00	1.66	9.99	(0.00)	9.99
Post construction cleaning.							
Totals: Bathroom			40.23	579.76	3,478.32	0.00	3,478.32



Shower Height: 8'

175.78 SF Walls 212.09 SF Walls & Ceiling 4.03 SY Flooring 24.33 LF Ceil. Perimeter

36.31 SF Floor21.50 LF Floor Perimeter

36.31 SF Ceiling

Missing Wall - Goes to Floor

2' 10" X 6' 8"

**Opens into BATHROOM** 

	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Walls							
26. Tear out wet paneling, bag for disposa	al 110.67 SF	0.70	0.60	15.62	93.69	(0.00)	93.69
Damaged paneling to be removed thro	ugh out where not	removed yet.					
27. R&R Sheathing - shiplap - cedar*	0.00 SF	11.17	0.00	0.00	0.00	(0.00)	0.00
Shiplap wood sheathing behind panelin	g in shower area i	s all damaged and	rotten, need t	o replace.			
28. HEPA Vacuuming - Detailed - (PER	175.78 SF	0.79	0.00	27.78	166.65	(0.00)	166.65
SF)							
Hepa vacuuming to be performed to ave	oid mold or bacter	rial growth since is	a water dama	ige.			
29. Paneling	97.33 SF	2.90	5.58	57.58	345.42	(0.00)	345.42
New paneling to be replaced over newly	y repalced sheathi	ng shiplap.					
30. Seal & paint paneling	97.33 SF	1.40	1.71	27.60	165.57	(0.00)	165.57
Miscellaneous							
31. R&R Stud wall - 2" x 4" x 8' - 16" oc	$4.00\mathrm{LF}$	24.37	2.03	19.88	119.39	(0.00)	119.39
Right wall of shower to be pushed back	to wider the show	er area, need to re	move it from i	ts current posi	tion and repla	ace at a little back	k
32. Carpenter - General Framer - per hour	4.00 HR	81.27	0.00	65.02	390.10	(0.00)	390.10
In moving that above stud wall, closet is		lease refer to pics	to confirm, th	is line item acc	ounts for lab	or to remove and	demolish
that small closet so that the stud wall can	be pushed back.						
Flooring							
33. R&R Joist - floor or ceiling - 2x10 -	18.16 SF	5.10	1.80	18.88	113.30	(0.00)	113.30
w/blocking - 16" oc A part of floor joist is missing and is a l	ittle damaged, nee	ed to replace for th	at, please refe	er to pics at lass	t to confirm		
P and of from the first of an an an an		The second of the second	, <sub>F</sub>				
				1	io conjirm.		
34. HEPA Vacuuming exposed framing -	36.31 SF	1.27	0.00	9.22	55.33	(0.00)	55.33
34. HEPA Vacuuming exposed framing - Floor - (PER SF) 35. R&R Underlayment - 5/8" OSB	36.31 SF 36.31 SF	1.27 2.98	0.00 2.70	-	-	(0.00)	55.33 133.08
Floor - (PER SF)				9.22	55.33		
Floor - (PER SF) 35. R&R Underlayment - 5/8" OSB Subfloor to be replaced.				9.22	55.33		
Floor - (PER SF) 35. R&R Underlayment - 5/8" OSB	36.31 SF	2.98	2.70	9.22 22.18	55.33 133.08	(0.00)	133.08
Floor - (PER SF) 35. R&R Underlayment - 5/8" OSB Subfloor to be replaced. 36. Tile floor covering Tile flooring with added wastage.	36.31 SF 41.76 SF	2.98 14.58	2.70 15.48	9.22 22.18 124.88	55.33 133.08 749.22	(0.00)	133.08 749.22
Floor - (PER SF) 35. R&R Underlayment - 5/8" OSB Subfloor to be replaced. 36. Tile floor covering	36.31 SF	2.98	2.70	9.22 22.18	55.33 133.08	(0.00)	133.08 749.22
Floor - (PER SF) 35. R&R Underlayment - 5/8" OSB Subfloor to be replaced. 36. Tile floor covering Tile flooring with added wastage. 37. Grout sealer	36.31 SF 41.76 SF	2.98 14.58	2.70 15.48	9.22 22.18 124.88	55.33 133.08 749.22	(0.00)	133.08 749.22 81.18
Floor - (PER SF) 35. R&R Underlayment - 5/8" OSB Subfloor to be replaced. 36. Tile floor covering Tile flooring with added wastage. 37. Grout sealer Trim	36.31 SF 41.76 SF 36.31 SF	2.98 14.58 1.85	2.70 15.48 0.47	9.22 22.18 124.88 13.54	55.33 133.08 749.22 81.18	(0.00)	133.08 749.22 81.18 177.00
Floor - (PER SF) 35. R&R Underlayment - 5/8" OSB Subfloor to be replaced. 36. Tile floor covering Tile flooring with added wastage. 37. Grout sealer Trim 38. R&R Crown molding - 3 1/4" 39. Paint crown molding - one coat Shower	36.31 SF 41.76 SF 36.31 SF 24.33 LF 24.33 LF	2.98 14.58 1.85 5.92 1.17	2.70 15.48 0.47 3.47 0.25	9.22 22.18 124.88 13.54 29.50 5.76	55.33 133.08 749.22 81.18 177.00 34.48	(0.00) (0.00) (0.00) (0.00) (0.00)	133.08 749.22 81.18 177.00 34.48
Floor - (PER SF)  35. R&R Underlayment - 5/8" OSB Subfloor to be replaced.  36. Tile floor covering Tile flooring with added wastage.  37. Grout sealer Trim 38. R&R Crown molding - 3 1/4" 39. Paint crown molding - one coat Shower 40. 1/4" Cement board	36.31 SF 41.76 SF 36.31 SF 24.33 LF	2.98 14.58 1.85 5.92	2.70 15.48 0.47 3.47	9.22 22.18 124.88 13.54 29.50	55.33 133.08 749.22 81.18 177.00	(0.00) (0.00) (0.00)	133.08
Floor - (PER SF) 35. R&R Underlayment - 5/8" OSB Subfloor to be replaced. 36. Tile floor covering Tile flooring with added wastage. 37. Grout sealer Trim 38. R&R Crown molding - 3 1/4" 39. Paint crown molding - one coat Shower	36.31 SF 41.76 SF 36.31 SF 24.33 LF 24.33 LF	2.98 14.58 1.85 5.92 1.17	2.70 15.48 0.47 3.47 0.25	9.22 22.18 124.88 13.54 29.50 5.76	55.33 133.08 749.22 81.18 177.00 34.48	(0.00) (0.00) (0.00) (0.00) (0.00)	133.08 749.22 81.18 177.00 34.48
Floor - (PER SF)  35. R&R Underlayment - 5/8" OSB Subfloor to be replaced.  36. Tile floor covering Tile flooring with added wastage.  37. Grout sealer Trim 38. R&R Crown molding - 3 1/4" 39. Paint crown molding - one coat Shower 40. 1/4" Cement board	36.31 SF 41.76 SF 36.31 SF 24.33 LF 24.33 LF	2.98 14.58 1.85 5.92 1.17	2.70 15.48 0.47 3.47 0.25	9.22 22.18 124.88 13.54 29.50 5.76	55.33 133.08 749.22 81.18 177.00 34.48	(0.00) (0.00) (0.00) (0.00) (0.00)	133.08 749.22 81.18 177.00 34.48

#### **CONTINUED - Shower**

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
42. Tile shower - 61 to 100 SF	1.00 EA	2,902.83	44.89	589.54	3,537.26	(0.00)	3,537.26
43. Shower base	1.00 EA	575.59	21.48	119.42	716.49	(0.00)	716.49
44. Rough-in plumbing - per fixture	1.00 EA	759.85	11.20	154.22	925.27	(0.00)	925.27
Plumbing needs to be done for shower, s	supply lines and	all to make it work					
45. Shower faucet	1.00 EA	248.16	8.78	51.40	308.34	(0.00)	308.34
46. Custom shower door & partition - 1/4' glass w/frame	40.00 SF	33.15	57.08	276.62	1,659.70	(0.00)	1,659.70
New shower door to be replaced.							
Final Cleaning							
47. Final cleaning - construction - Residential	36.31 SF	0.34	0.00	2.48	14.83	(0.00)	14.83
Totals: Shower			199.68	1,843.92	11,063.10	0.00	11,063.10
Total: Main Level			239.91	2,423.68	14,541.42	0.00	14,541.42
Debri	s Removal						
DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
48. Haul debris - per pickup truck load - including dump fees	1.00 EA	178.81	0.00	35.76	214.57	(0.00)	214.57
Totals: Debris Removal			0.00	35.76	214.57	0.00	214.57
Labor Minimums Applied							
DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
49. Electrical labor minimum	1.00 EA	179.22	0.00	35.84	215.06	(0.00)	215.06
50. Drywall labor minimum	1.00 EA	315.85	0.00	63.18	379.03	(0.00)	379.03
51. Cleaning labor minimum*	1.00 EA	77.42	0.00	15.48	92.90	(0.00)	92.90
52. Cabinetry labor minimum	1.00 EA	72.54	0.00	14.50	87.04	(0.00)	87.04
53. Finish carpentry labor minimum	1.00 EA	77.09	0.00	15.42	92.51	(0.00)	92.51
54. Siding labor minimum	1.00 EA	361.77	0.00	72.36	434.13	(0.00)	434.13

### **CONTINUED - Labor Minimums Applied**

DESCRIPTION	Qī	UANTITY UN	IT PRICE T	AX	O&P	RC	V DEPREC.	ACV
Totals: Labor Minimums	s Applied		0	0.00	216.78	1,300.6	7 0.00	1,300.67
Line Item Totals: 110-N-	CHESTNUT-ST		239	0.91	2,676.22	16,056.6	6 0.00	16,056.66
<b>Grand Total Areas</b>	:							
690.22 SF Walls	S	124.21	SF Ceiling		814	.43 SF V	Walls and Ceiling	
124.21 SF Floor		13.80	SY Flooring		85	.33 LF I	Floor Perimeter	
0.00 SF Long	Wall	0.00	SF Short Wall		91	.00 LF (	Ceil. Perimeter	
124.21 Floor Ar	ea	150.57	Total Area		690	.22 Inter	rior Wall Area	
586.50 Exterior	Wall Area	65.17	Exterior Perimeter Walls	of				
0.00 Surface	Area	0.00	Number of Square	s	0	.00 Tota	al Perimeter Lengt	h
0.00 Total Ric	dge Length	0.00	Total Hip Length					

Summary	for	Dwe	lling
Summa v	101	$\mathbf{D}_{\mathbf{W}}$	111112

Line Item Total	13,140.53
Material Sales Tax	239.91
Subtotal	13,380.44
Overhead	1,338.11
Profit	1,338.11
Replacement Cost Value	\$16,056.66
Net Claim	\$16,056.66

Office

### Recap of Taxes, Overhead and Profit

Over	Overhead (10%) Profit (10%)		verhead (10%) Profit (10%)		Material Sales Tax (6.75%)	Laundry & D/C Tax (6.75%)	Manuf. Home Tax (4.75%)	Storage Rental Tax (6.75%)	Local Food Tax (2%)
Line Items									
	1,338.11	1,338.11	239.91	0.00	0.00	0.00	0.00		
Total									
	1,338.11	1,338.11	239.91	0.00	0.00	0.00	0.00		

## **Recap by Room**

**Estimate: 110-N-CHESTNUT-ST** 

Area: Main Level		
Bathroom	2,858.33	21.75%
Shower	9,019.50	68.64%
Area Subtotal: Main Level	11,877.83	90.39%
Debris Removal	178.81	1.36%
Labor Minimums Applied	1,083.89	8.25%
Subtotal of Areas	13,140.53	100.00%
Total	13,140.53	100.00%

# **Recap by Category**

O&P Items	Total	%
CABINETRY	206.84	1.29%
CLEANING	135.80	0.85%
GENERAL DEMOLITION	517.71	3.22%
DRYWALL	462.18	2.88%
ELECTRICAL	179.22	1.12%
FLOOR COVERING - CERAMIC TILE	1,539.74	9.59%
FINISH CARPENTRY / TRIMWORK	271.09	1.69%
FRAMING & ROUGH CARPENTRY	612.44	3.81%
LIGHT FIXTURES	116.32	0.72%
MIRRORS & SHOWER DOORS	1,326.00	8.26%
PLUMBING	2,514.36	15.66%
PANELING & WOOD WALL FINISHES	579.34	3.61%
PAINTING	502.20	3.13%
SIDING	361.77	2.25%
TILE	3,537.15	22.03%
WATER EXTRACTION & REMEDIATION	278.37	1.73%
O&P Items Subtotal	13,140.53	81.84%
Material Sales Tax	239.91	1.49%
Overhead	1,338.11	8.33%
Profit	1,338.11	8.33%
Total	16,056.66	100.00%



1 1-Vanity wall
Vanity wall where drywall is all damaged, need to replace.



2 2-Closet behind shower right wallCloset behind shower area wall (which is to displace from its current position)




3 3-Floor joist damage Floor joist damaged/missing in shower area.




4 4-Shiplap behind paneling damage shower


Wood behind paneling in shower area is all damaged and rotten, need to replace



5 5-Paneling damage
Paneling damaged in bathroom, wet and detriorated, need to replace



6 6-Plumbing
Plumbing to be done for vanity as well as for shower.





# Main Level

110-N-CHESTNUT-ST Page: 17