


Main RF branch



OOB branch



OOB-guided fusion

$$Q = T_m, K, V = T_o$$
$$A = \text{MHA}(Q, K, V)$$
$$T_f = \text{LN}(T_m + G \odot A W_o)$$

$$P = 32, D = 64$$