

Telecom Egypt Internal Technical Support Knowledge Base (Confidential)

1. General Service Level Agreement (SLA) & Dispatch Policies

If a customer reports an internet outage (DSL blinking or no sync):

- The L1 agent must first ensure the customer has restarted the router and checked internal wiring.
- If the issue persists for more than 24 hours, the L1 agent must escalate to the Central Exchange team.
- A Field Technician must be dispatched if the line noise margin is below 6dB or if the DSL light is completely off/blinking for 3 consecutive days.
- The customer must be informed that the technician will contact them within 48 working hours.
- Compensation of 5GB mobile data is authorized ONLY if the outage exceeds 72 hours.

2. Hardware Specifications & Router Guides

Router Model: VDF-ZTE-2023X1

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2023X2

- **Manufacturer:** Huawei
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2025X3

- **Manufacturer:** ZTE
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-CIS-2024X4

- **Manufacturer:** Cisco
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-NOK-2022X5

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-NOK-2023X6

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-NOK-2026X7

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2020X8

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2021X9

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2021X10

- **Manufacturer:** Huawei
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2024X11

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2022X12

- **Manufacturer:** Huawei
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-TP--2023X13

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-NOK-2020X14

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2021X15

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2022X16

- **Manufacturer:** Huawei
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-NOK-2026X17

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2022X18

- **Manufacturer:** Nokia
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-NOK-2025X19

- **Manufacturer:** Nokia
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2026X20

- **Manufacturer:** Huawei
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-TP--2021X21

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2021X22

- **Manufacturer:** ZTE
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2021X23

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-TP--2026X24

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2022X25

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2021X26

- **Manufacturer:** ZTE
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2026X27

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2023X28

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-TP--2025X29

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2021X30

- **Manufacturer:** ZTE
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2026X31

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-TP--2021X32

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2023X33

- **Manufacturer:** ZTE
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2025X34

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2020X35

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2026X36

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2024X37

- **Manufacturer:** ZTE
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-ZTE-2021X38

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2025X39

- **Manufacturer:** Huawei
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2022X40

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2025X41

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2020X42

- **Manufacturer:** ZTE
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2022X43

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-ZTE-2021X44

- **Manufacturer:** ZTE
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2020X45

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-TP--2020X46

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2024X47

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2020X48

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2025X49

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2026X50

- **Manufacturer:** ZTE
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2022X51

- **Manufacturer:** Huawei
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-TP--2022X52

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2024X53

- **Manufacturer:** Nokia
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2025X54

- **Manufacturer:** ZTE
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-NOK-2021X55

- **Manufacturer:** Nokia
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2021X56

- **Manufacturer:** Huawei
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-CIS-2026X57

- **Manufacturer:** Cisco
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2025X58

- **Manufacturer:** Huawei
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2021X59

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2024X60

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2025X61

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-ZTE-2024X62

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-CIS-2025X63

- **Manufacturer:** Cisco
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2026X64

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-TP--2022X65

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-NOK-2026X66

- **Manufacturer:** Nokia
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2020X67

- **Manufacturer:** Huawei
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2021X68

- **Manufacturer:** Huawei
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2023X69

- **Manufacturer:** Nokia
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2023X70

- **Manufacturer:** ZTE
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-CIS-2024X71

- **Manufacturer:** Cisco
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-TP--2020X72

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-TP--2023X73

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2024X74

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2021X75

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-TP--2024X76

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2023X77

- **Manufacturer:** Nokia
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2021X78

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-TP--2021X79

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2021X80

- **Manufacturer:** Nokia
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2023X81

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2021X82

- **Manufacturer:** Nokia
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-TP--2022X83

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-CIS-2025X84

- **Manufacturer:** Cisco
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-CIS-2020X85

- **Manufacturer:** Cisco
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-TP--2024X86

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2023X87

- **Manufacturer:** Huawei
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-TP--2020X88

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-NOK-2020X89

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-ZTE-2025X90

- **Manufacturer:** ZTE
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2025X91

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2024X92

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-TP--2024X93

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-CIS-2024X94

- **Manufacturer:** Cisco
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-NOK-2020X95

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2024X96

- **Manufacturer:** Huawei
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2026X97

- **Manufacturer:** Huawei
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2025X98

- **Manufacturer:** ZTE
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2020X99

- **Manufacturer:** Nokia
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2021X100

- **Manufacturer:** Huawei
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-TP--2026X101

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-CIS-2023X102

- **Manufacturer:** Cisco
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2023X103

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2024X104

- **Manufacturer:** Nokia
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-CIS-2021X105

- **Manufacturer:** Cisco
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-TP--2026X106

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-TP--2020X107

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-CIS-2021X108

- **Manufacturer:** Cisco
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2026X109

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-CIS-2023X110

- **Manufacturer:** Cisco
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2024X111

- **Manufacturer:** ZTE
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-CIS-2023X112

- **Manufacturer:** Cisco
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2024X113

- **Manufacturer:** Huawei
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2020X114

- **Manufacturer:** Huawei
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2021X115

- **Manufacturer:** Huawei
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-ZTE-2025X116

- **Manufacturer:** ZTE
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2023X117

- **Manufacturer:** Huawei
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2020X118

- **Manufacturer:** Huawei
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-TP--2020X119

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-TP--2025X120

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2021X121

- **Manufacturer:** Huawei
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-TP--2022X122

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2025X123

- **Manufacturer:** Huawei
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-TP--2023X124

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2025X125

- **Manufacturer:** Nokia
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2020X126

- **Manufacturer:** Nokia
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-TP--2024X127

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-CIS-2023X128

- **Manufacturer:** Cisco
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-CIS-2026X129

- **Manufacturer:** Cisco
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2021X130

- **Manufacturer:** Huawei
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2023X131

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2020X132

- **Manufacturer:** Nokia
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2020X133

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2020X134

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-CIS-2022X135

- **Manufacturer:** Cisco
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-CIS-2022X136

- **Manufacturer:** Cisco
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-ZTE-2024X137

- **Manufacturer:** ZTE
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-CIS-2026X138

- **Manufacturer:** Cisco
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2025X139

- **Manufacturer:** Huawei
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2024X140

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-CIS-2026X141

- **Manufacturer:** Cisco
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-TP--2020X142

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2022X143

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2021X144

- **Manufacturer:** Nokia
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2021X145

- **Manufacturer:** Nokia
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-CIS-2021X146

- **Manufacturer:** Cisco
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-CIS-2024X147

- **Manufacturer:** Cisco
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2024X148

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-ZTE-2020X149

- **Manufacturer:** ZTE
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2022X150

- **Manufacturer:** ZTE
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2025X151

- **Manufacturer:** Huawei
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-CIS-2024X152

- **Manufacturer:** Cisco
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2020X153

- **Manufacturer:** Nokia
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-TP--2026X154

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-TP--2021X155

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-TP--2023X156

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2021X157

- **Manufacturer:** ZTE
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2025X158

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-CIS-2022X159

- **Manufacturer:** Cisco
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2025X160

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-CIS-2025X161

- **Manufacturer:** Cisco
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-CIS-2024X162

- **Manufacturer:** Cisco
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-TP--2020X163

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-TP--2023X164

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2023X165

- **Manufacturer:** Huawei
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2021X166

- **Manufacturer:** ZTE
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2026X167

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2024X168

- **Manufacturer:** Huawei
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-HUA-2020X169

- **Manufacturer:** Huawei
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-CIS-2022X170

- **Manufacturer:** Cisco
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2021X171

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-TP--2020X172

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-NOK-2022X173

- **Manufacturer:** Nokia
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2023X174

- **Manufacturer:** ZTE
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2023X175

- **Manufacturer:** Huawei
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-TP--2020X176

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-TP--2023X177

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-CIS-2023X178

- **Manufacturer:** Cisco
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2021X179

- **Manufacturer:** ZTE
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2022X180

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2020X181

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-CIS-2022X182

- **Manufacturer:** Cisco
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-TP--2026X183

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-CIS-2020X184

- **Manufacturer:** Cisco
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-HUA-2026X185

- **Manufacturer:** Huawei
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-TP--2020X186

- **Manufacturer:** TP-Link
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-HUA-2021X187

- **Manufacturer:** Huawei
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2021X188

- **Manufacturer:** ZTE
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-NOK-2025X189

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2023X190

- **Manufacturer:** Nokia
- **Max Supported Speed:** 1 Gbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2023X191

- **Manufacturer:** ZTE
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-CIS-2026X192

- **Manufacturer:** Cisco
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-ZTE-2023X193

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2022X194

- **Manufacturer:** Nokia
- **Max Supported Speed:** 30 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-NOK-2025X195

- **Manufacturer:** Nokia
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 35.

Router Model: VDF-ZTE-2025X196

- **Manufacturer:** ZTE
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 10.

Router Model: VDF-CIS-2021X197

- **Manufacturer:** Cisco
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2020X198

- **Manufacturer:** ZTE
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds.
Reconfigure with VLAN ID 20.

Router Model: VDF-ZTE-2025X199

- **Manufacturer:** ZTE
- **Max Supported Speed:** 200 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.

- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds. Reconfigure with VLAN ID 20.

Router Model: VDF-CIS-2023X200

- **Manufacturer:** Cisco
- **Max Supported Speed:** 100 Mbps
- **DSL Light Behavior:** If blinking, indicates failure to sync with the central exchange. If solid green, sync is successful. If red, physical line cut.
- **Internet Light Behavior:** If red, authentication failure (wrong PPPoE username/password). If off, no IP assigned.
- **Troubleshooting Step 1:** Restart router and wait 2 minutes.
- **Troubleshooting Step 2:** Factory reset by holding the reset pin for 10 seconds. Reconfigure with VLAN ID 35.

3. Network Error Codes Database

Error Code E-100

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-101

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-102

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-103

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-104

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-105

Description: IP Allocation Failure **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-106

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-107

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-108

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-109

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-110

Description: Port Disabled at Central **Resolution Protocol:** Dispatch Field Technician

Error Code E-111

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-112

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-113

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-114

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-115

Description: DNS Resolution Error **Resolution Protocol:** Dispatch Field Technician

Error Code E-116

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-117

Description: DNS Resolution Error **Resolution Protocol:** Dispatch Field Technician

Error Code E-118

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-119

Description: IP Allocation Failure **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-120

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-121

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-122

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-123

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-124

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-125

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-126

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-127

Description: Port Disabled at Central **Resolution Protocol:** Dispatch Field Technician

Error Code E-128

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-129

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-130

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-131

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-132

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-133

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-134

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-135

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-136

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-137

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-138

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-139

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-140

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-141

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-142

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-143

Description: Port Disabled at Central **Resolution Protocol:** Dispatch Field Technician

Error Code E-144

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-145

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-146

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-147

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-148

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-149

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-150

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-151

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-152

Description: DNS Resolution Error **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-153

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-154

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-155

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-156

Description: DNS Resolution Error **Resolution Protocol:** Dispatch Field Technician

Error Code E-157

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-158

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-159

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-160

Description: Port Disabled at Central **Resolution Protocol:** Reset port via CRM

Error Code E-161

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-162

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-163

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-164

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-165

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-166

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-167

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-168

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-169

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-170

Description: Port Disabled at Central **Resolution Protocol:** Dispatch Field Technician

Error Code E-171

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-172

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-173

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-174

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-175

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-176

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-177

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-178

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-179

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-180

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-181

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-182

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-183

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-184

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-185

Description: Port Disabled at Central **Resolution Protocol:** Reset port via CRM

Error Code E-186

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-187

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-188

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-189

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-190

Description: DNS Resolution Error **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-191

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-192

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-193

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-194

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-195

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-196

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-197

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-198

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-199

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-200

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-201

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-202

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-203

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-204

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-205

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-206

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-207

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-208

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-209

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-210

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-211

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-212

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-213

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-214

Description: Port Disabled at Central **Resolution Protocol:** Dispatch Field Technician

Error Code E-215

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-216

Description: Port Disabled at Central **Resolution Protocol:** Reset port via CRM

Error Code E-217

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-218

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-219

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-220

Description: Port Disabled at Central **Resolution Protocol:** Reset port via CRM

Error Code E-221

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-222

Description: Port Disabled at Central **Resolution Protocol:** Dispatch Field Technician

Error Code E-223

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-224

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-225

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-226

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-227

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-228

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-229

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-230

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-231

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-232

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-233

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-234

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-235

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-236

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-237

Description: IP Allocation Failure **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-238

Description: IP Allocation Failure **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-239

Description: Port Disabled at Central **Resolution Protocol:** Dispatch Field Technician

Error Code E-240

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-241

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-242

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-243

Description: DNS Resolution Error **Resolution Protocol:** Dispatch Field Technician

Error Code E-244

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-245

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-246

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-247

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-248

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-249

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-250

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-251

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-252

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-253

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-254

Description: DNS Resolution Error **Resolution Protocol:** Dispatch Field Technician

Error Code E-255

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-256

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-257

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-258

Description: DNS Resolution Error **Resolution Protocol:** Dispatch Field Technician

Error Code E-259

Description: DNS Resolution Error **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-260

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-261

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-262

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-263

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-264

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-265

Description: Port Disabled at Central **Resolution Protocol:** Reset port via CRM

Error Code E-266

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-267

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-268

Description: DNS Resolution Error **Resolution Protocol:** Dispatch Field Technician

Error Code E-269

Description: Port Disabled at Central **Resolution Protocol:** Dispatch Field Technician

Error Code E-270

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-271

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-272

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-273

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-274

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-275

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-276

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-277

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-278

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-279

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-280

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-281

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-282

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-283

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-284

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-285

Description: DNS Resolution Error **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-286

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-287

Description: DNS Resolution Error **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-288

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-289

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-290

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-291

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-292

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-293

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-294

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-295

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-296

Description: IP Allocation Failure **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-297

Description: DNS Resolution Error **Resolution Protocol:** Dispatch Field Technician

Error Code E-298

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-299

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-300

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-301

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-302

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-303

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-304

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-305

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-306

Description: DNS Resolution Error **Resolution Protocol:** Dispatch Field Technician

Error Code E-307

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-308

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-309

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-310

Description: Port Disabled at Central **Resolution Protocol:** Dispatch Field Technician

Error Code E-311

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-312

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-313

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-314

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-315

Description: Port Disabled at Central **Resolution Protocol:** Reset port via CRM

Error Code E-316

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-317

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-318

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-319

Description: IP Allocation Failure **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-320

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-321

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-322

Description: DNS Resolution Error **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-323

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-324

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-325

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-326

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-327

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-328

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-329

Description: DNS Resolution Error **Resolution Protocol:** Dispatch Field Technician

Error Code E-330

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-331

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-332

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-333

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-334

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-335

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-336

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-337

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-338

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-339

Description: IP Allocation Failure **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-340

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-341

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-342

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-343

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-344

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-345

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-346

Description: Authentication Timeout **Resolution Protocol:** Reset port via CRM

Error Code E-347

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-348

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-349

Description: Port Disabled at Central **Resolution Protocol:** Reset port via CRM

Error Code E-350

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-351

Description: Port Disabled at Central **Resolution Protocol:** Reset port via CRM

Error Code E-352

Description: Line Noise Too High **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-353

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-354

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-355

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-356

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-357

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-358

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-359

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-360

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-361

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-362

Description: DNS Resolution Error **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-363

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-364

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-365

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-366

Description: IP Allocation Failure **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-367

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-368

Description: Port Disabled at Central **Resolution Protocol:** Reset port via CRM

Error Code E-369

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-370

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-371

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-372

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-373

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-374

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-375

Description: Port Disabled at Central **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-376

Description: Port Disabled at Central **Resolution Protocol:** Dispatch Field Technician

Error Code E-377

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-378

Description: IP Allocation Failure **Resolution Protocol:** Dispatch Field Technician

Error Code E-379

Description: Port Disabled at Central **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-380

Description: DNS Resolution Error **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-381

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-382

Description: Authentication Timeout **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-383

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-384

Description: DNS Resolution Error **Resolution Protocol:** Reset port via CRM

Error Code E-385

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-386

Description: DNS Resolution Error **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-387

Description: IP Allocation Failure **Resolution Protocol:** Reset port via CRM

Error Code E-388

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-389

Description: DNS Resolution Error **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-390

Description: Line Noise Too High **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-391

Description: IP Allocation Failure **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-392

Description: Port Disabled at Central **Resolution Protocol:** Dispatch Field Technician

Error Code E-393

Description: DNS Resolution Error **Resolution Protocol:** Instruct customer to change DNS to 8.8.8.8

Error Code E-394

Description: Port Disabled at Central **Resolution Protocol:** Dispatch Field Technician

Error Code E-395

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

Error Code E-396

Description: Authentication Timeout **Resolution Protocol:** Escalate to Tier 2 Network Ops

Error Code E-397

Description: Line Noise Too High **Resolution Protocol:** Reset port via CRM

Error Code E-398

Description: Authentication Timeout **Resolution Protocol:** Dispatch Field Technician

Error Code E-399

Description: Line Noise Too High **Resolution Protocol:** Dispatch Field Technician

4. Cross-Department Escalation Matrix

- **Billing Issues:** Transfer to 111.
- **Fiber Optic Cuts:** Escalate immediately to Tier 3 Fiber Ops. SLA is 12 hours.
- **Mass Outage (Area Level):** Do not dispatch individual technicians. Read the 'Global Outage Script' to the customer.