k	deviceid	unitno	deviceip	mh02status	modem_cpe	power	last_update	note	date_created
	SDLIR011	DT4090	10.187.128.55	terpasang	terpasang	true			
	SDLIR012	FT290	10.187.128.11	terpasang	terpasang	true			
	SDLIR014	DT3670	10.187.128.141	terpasang	terpasang	true			
	SDLIR034	LD2011	10.187.128.19	terpasang	terpasang	true			
	SLS301002	DT3894	10.187.128.56	terpasang	terpasang	true			
	SLS301003	DT4738	10.187.128.66	terpasang	terpasang	true			
	SLS301004	LD2009	10.187.128.127	terpasang	terpasang	true			
	SLS301005	DT3709	10.187.128.85	terpasang	terpasang	true	00.06.2025		2025 06 00 12 26 47
	SLS301006	HM1805	10.187.128.204	terpasang	-	true	09-06-2025		2025-06-09 13:36:47
	SLS301007	DT3981	10.187.128.92	terpasang	terpasang	true	00.06.0005		2025 06 00 12 27 10
	SLS301008	HM1658	10.187.128.205	terpasang	-	true	09-06-2025		2025-06-09 13:37:19
	SLS301009	LD780	10.187.128.118	terpasang	terpasang	true	11-06-2025		2025-06-11 22:03:06
	SLS30I010	LD838G	10.187.128.106	terpasang	terpasang	true			
	SLS30I011	DT4825	10.187.128.20	terpasang	terpasang	true			
	SLS30I012	LD823	10.187.128.8	terpasang	terpasang	true			
	SLS30I013	DT4103	10.187.128.88	terpasang	terpasang	true			
	SLS30I014	HM1806	10.187.128.201	terpasang	terpasang	true			
	SLS30I017	-	10.187.128.145	rusak	-	false	13-06-2025	Kebal Lan tidak lengkap/Braket lama	2025-06-13 14:37:46
	SLS30I018	LD3115	10.187.128.103	terpasang	terpasang	true			
	SLS30I019	DT3915	10.187.128.68	terpasang	terpasang	true			
	SLS30I021	LD3111	10.187.128.38	terpasang	terpasang	true			
	SLS30I023	LD3105	10.187.128.12	terpasang	terpasang	true			
	SLS30I026	PM709	10.187.128.33	terpasang	terpasang	true			
	SLS30I029	DT5713	10.187.128.90	terpasang	terpasang	true	25-05-2025		
	SLS30I033	PM708	10.187.128.115	terpasang	terpasang	true			
	SLS30I042	PM703	-	terpasang	-	true	02-06-2025		
	SLS301068	DN7472	10.187.128.175	terpasang	terpasang	true			
	SLS301069	DT5859	10.187.128.109	terpasang	terpasang	true			
	SLS301070	LD2001	10.187.128.61	terpasang	terpasang	true			
	SLS30I071	LD3112	10.187.128.74	terpasang	terpasang	true			
1 9	SLS301072	LD2017	10.187.128.36	terpasang	terpasang	true			
2 9	SLS30I073	PM719	10.187.128.136	terpasang	terpasang	true			
3 9	SLS30I074	FT190	10.187.128.158	terpasang	terpasang	true			
4 5	SLS30I075	DT5041	10.187.128.69	terpasang	terpasang	true			
5 5	SLS301083	DT3296	10.187.128.139	terpasang	terpasang	true			
	SLS30I094	LD825	10.187.128.7	terpasang	terpasang	true			
7 9	SLS301095	LD2007	10.187.128.114	terpasang	terpasang	true			
8 9	SLS301096	DT4128	10.187.128.63	terpasang	terpasang	true			
9 9	SLS301097	LD3127	10.187.128.226	terpasang	terpasang	true	09-06-2025		2025-06-09 13:52:34
0 5	SLS301098	LD822	10.187.128.76	terpasang	terpasang	true			
1 9	SLS301099	LD2018	10.187.128.28	terpasang	terpasang	true			
2 5	SLS30I100	LD837G	10.187.128.102	terpasang	terpasang	true			
3 9	SLS30I111	DT4725	10.187.128.138	terpasang	terpasang	true			
1 5	SLS30I112	-	10.187.128.196	rusak	-	false	13-06-2025	dari LV tidak ada SPM/Braket lama	2025-06-13 14:33:38
5 5	SLS30I114	LD826	10.187.128.54	terpasang	terpasang	true			
6 9	SLS30I115	DT5872	10.187.128.111	terpasang	terpasang	true			
	SLS30I116	LD3108	10.187.128.18	terpasang	terpasang	true			
	SLS30I117	LD3109	10.187.128.130	terpasang	terpasang	true			
	SLS30I118	-	10.187.128.60	rusak	-	true	12-06-2025		2025-06-12 12:18:31
	SLS30I119	-	10.187.128.48	rusak	-	true	12-06-2025		2025-06-12 12:17:51
	SLS30I120	HM1756	10.187.128.183	terpasang	terpasang	true			
	SLS30I121	DT5732	10.187.128.71	terpasang	terpasang	true			
	SLS30I122	HM1655	10.187.128.188	terpasang	terpasang	true			
	SLS30I123	DT4119	10.187.128.27	terpasang	terpasang	true			
	SLS30I124	LD3107	10.187.128.146	terpasang	terpasang	true			
	SLS30I138	-	10.187.128.126	standby	-	false	30-05-2025	butuh speaker ext	
	SLS30I139	DT5256	10.187.128.72	terpasang	terpasang	true			
	SLS30I140	DT4055	10.187.128.142	terpasang	terpasang	true			
	SLS30I141	DT5857	10.187.128.112	terpasang	terpasang	true			
	SLS30I142	DT5869	10.187.128.107	terpasang	terpasang	true	11-06-2025		2025-06-11 15:52:49
	SLS30I143	PM711	10.187.128.155	terpasang	terpasang	true			
	SLS30I144	DT3980	10.187.128.93	terpasang	terpasang	true			
	SLS30I145	PM710	10.187.128.154	terpasang	terpasang	true			
	SLS30I113 SLS30I147	DT4122	10.187.128.95	terpasang	terpasang	true			
	SLS30I117 SLS30I148	DT3715	10.187.128.134	terpasang	terpasang	true			
	SLS301140 SLS301149	LD3106	10.187.128.29	terpasang	terpasang	true			
	SLS301143 SLS301151	-	10.187.128.117	rusak	-	false	13-06-2025	SPM tidak lengkap/Braket lama	2025-06-13 14:39:47
	SLS30I151 SLS30I153	DT3714	10.187.128.10	terpasang	terpasang	true		5 Guar tengrap/brance fullia	2023 00 13 17.33.77
	SLS30I153 SLS30I154	DT4051	10.187.128.144	terpasang	terpasang	true			
	SLS301154 SLS301155	DT5967	10.187.128.178	terpasang					
115		013301	10.107.120.170	ter pasarity	terpasang Page n	imhor	1//		Jun 18, 2025

Jun 18, 2025 at 02:33 PM

d	deviceid	unitno	deviceip	mh02status	modem_cpe	power	last_update	note	date_created
	SLS30I156	DT5062	10.187.128.44	terpasang	terpasang	true			
	SLS30I190	LD3116	10.187.128.37	terpasang	terpasang	true			
	SLS30I192	LD829	10.187.128.94	terpasang	terpasang	true			
	SLS30I193	LD2008	10.187.128.120	terpasang	terpasang	true	00.06.2025		2025 00 00 12 20 07
	SLS30I194	HM1821	10.187.128.203	terpasang	-	true	09-06-2025		2025-06-09 13:36:07
	SLS30I195	LD3114	10.187.128.16	terpasang	terpasang	true			
	SLS30I196 SLS30I197	LD3110 LD3126	10.187.128.46	terpasang	terpasang	true	25-05-2025	mh02 lemot	
	SLS301197 SLS301199	LD3126	10.187.128.13	terpasang	tornacana	true	23-03-2023	minoz iemot	
	SLS301299 SLS301200	LD3116	10.187.128.135	terpasang terpasang	terpasang	true			
	SLS301200 SLS301201	LO185	10.187.128.100	terpasang	terpasang terpasang	true			
	SLS301201 SLS301202	LD3119	10.187.128.22	terpasang	terpasang	true			
	SLS30I202	LD828	10.187.128.47	terpasang	terpasang	true			
	SLS30I205	LD3120	10.187.128.17	terpasang	terpasang	true			
	SLS30I205	LD2002	10.187.128.40	terpasang	-	true	09-06-2025		2025-06-09 13:42:05
	SLS30I200	LD827	10.187.128.45	terpasang	terpasang	true	03 00 2023		2023 00 03 13.42.03
	SLS30I210	HM1799	10.187.128.176	terpasang	terpasang	true			
	SLS30I211	-	10.187.128.90	kembali ke HO	-	false	25-05-2025		
	SLS30I212	DT3671	10.187.128.143	terpasang	terpasang	true			
	SLS30I212	LD2004	10.187.128.15	terpasang	terpasang	true			
	SLS30I214	DT4106	10.187.128.49	terpasang	terpasang	true			
	SLS30I216	LD820G	10.187.128.6	terpasang	terpasang	true			
	SLS30I219	LD2005	10.187.128.119	terpasang	terpasang	true			
	SLS30I220	DT5069	10.187.128.32	terpasang	terpasang	true			
	SLS30I221	DT5638	10.187.128.2	terpasang	terpasang	true			
96 5	SLS30I236	HM1657	10.187.144.200	terpasang	terpasang	true			
97 5	SLS30I275	DT3858	10.187.128.129	terpasang	terpasang	true			
98 5	SLS30I283	DT4372	10.187.128.64	terpasang	terpasang	true			
	SLS30I285	PM721	10.187.128.31	terpasang	terpasang	true			
	SLS30I286	DT5258	10.187.128.84	terpasang	terpasang	true			
	SLS30I289	DT5180	10.187.128.50	terpasang	terpasang	true			
	SLS30I290	LD2003	10.187.128.14	terpasang	terpasang	true			
	SLS30I291	DT5601	10.187.128.78	terpasang	terpasang	true			
	SLS30I305	HM1638	10.187.128.181	terpasang	terpasang	true			
	SLS30I306	DT5746	10.187.128.83	terpasang	terpasang	true			
	SLS30I307	PM713	10.187.128.96	terpasang	terpasang	true			
	SLS30I308	DT5060	10.187.128.9	terpasang	terpasang	true			
	SLS30I310	LD2019	10.187.128.5	terpasang	terpasang	true			
	SLS30I311	DT3918	10.187.128.80	terpasang	terpasang	true			
	SLS30I312	DT3689	10.187.128.57	terpasang	terpasang	true			
	SLS30I313	DT4240	10.187.128.81	terpasang	terpasang	true			
	SLS30I314	LD821	10.187.128.21	terpasang	terpasang	true			
	SLS30I315	DT5871	10.187.128.108	terpasang	terpasang	true			
	SLS30I316	DT5858	10.187.128.82	terpasang	terpasang	true			
	SLS30I317	DT4610	10.187.128.73	terpasang	terpasang	true			
	SLS30I318	PM726	10.187.128.99	terpasang	terpasang	true			
	SLS30I319	PM712	10.187.128.101	terpasang	terpasang	true			
	SLS30I320	PM720	10.187.128.98	terpasang	terpasang	true			
	SLS30I321	LD836G	10.187.128.128	terpasang	terpasang	true			
	SLS30I322 SLS30I323	FT249 LD2000	10.187.128.156 10.187.128.229	terpasang	terpasang	true	11-06-2025		2025-06-11 15:10:13
	5LS30I323 5LS30I324	LD2000 LD835G	10.187.128.229	terpasang	terpasang	true	11-00-2023		2025-00-11 15:10:13
	SLS301324 SLS301325	PM715	10.187.128.125	terpasang terpasang	terpasang terpasang	true			
	SLS301325 SLS301326	DT5181	10.187.128.43	terpasang		true		+	
	SLS301320 SLS301327	- 013101	10.187.128.183	rusak	terpasang	true	13-06-2025	dari LV tidak ada SPM	2025-06-13 14:45:49
	SLS301327 SLS301328	LD830G	10.187.128.65	terpasang	terpasang	true	13-00-2023	duii LV tiuak aud JFIVI	2023-00-13 14.43.49
	SLS301328	LD831	10.187.128.104	terpasang	terpasang	true			
	SLS301329 SLS301330	LD834	10.187.128.104	terpasang	terpasang	true			
	SLS30I330 SLS30I331	LD833	10.187.128.122	terpasang	terpasang	true			
	SLS301331 SLS301332	PM714	10.187.128.123	terpasang	terpasang	true			
	SLS301332 SLS301333	PM722	10.187.128.105	terpasang	terpasang	true			
	SLS301333 SLS301334	DT4053	10.187.128.26	terpasang	terpasang	true			
	SLS301334 SLS301335	PM608	10.187.128.193	terpasang	terpasang	true			
	SLS301335	PM723	10.187.128.133	terpasang	terpasang	true			
	SLS301330 SLS301337	HM1652	10.187.128.190	terpasang	terpasang	true			
	SLS301337 SLS301338	DT4338	10.187.128.148	terpasang	terpasang	true			
	SLS301336 SLS301339	PM605	10.187.128.148	terpasang	terpasang	true			
	SLS301339 SLS301340	PM628	10.187.128.192	terpasang	terpasang	true			
	SLS30I340 SLS30I341	FT224	10.187.128.52	terpasang	terpasang	true			
13915		1 1 4 4 7	1 - 0 - 1 0 1 - 1 - 0 - 0 - 0	CCIDUSUIU	LCIDUJUIU	- G G C	· ·		I I

Jun 18, 2025 at 02:33 PM

id deviceid	unitno	deviceip	mh02status	modem_cpe	power	last_update	note	date_created
L41 SLS30I343	PM616	10.187.128.191	terpasang	terpasang	true			
.42 SLS30I344	PM724	10.187.128.149	terpasang	terpasang	true			
43 SLS30I345	PM624	10.187.128.194	terpasang	terpasang	true			
.44 SLS30I346 .45 SLS30I347	PM718 FT259	10.187.128.132 10.187.128.157	terpasang	terpasang	true			
.46 SLS30I408	DT5179	10.187.128.25	terpasang terpasang	terpasang terpasang	true true			
L47 SLS30I409	DT3712	10.187.128.77	terpasang	terpasang	true			
.48 SLS30I410	DT5663	10.187.128.42	terpasang	terpasang	true			
149 SLS30I411	LD2016	10.187.128.23	terpasang	terpasang	true			
L50 SLS30I476	CT141	10.187.128.79	terpasang	terpasang	true			
.51 SLS30I477	LD778	-	terpasang	terpasang	true	15-06-2025		2025-06-15 23:19:58
.52 SLS30I478	-	10.187.128.1	rusak	-	false	13-06-2025	Braket lama	2025-06-13 14:34:47
.53 SLS30I479	LO158	10.187.128.166	terpasang	terpasang	true			
.54 SLS30I480	CT157	10.187.128.160	terpasang	terpasang	true			
.55 SLS30I481	DT5719	10.187.128.70	terpasang	terpasang	true			
.56 SLS30I482	WT185	10.187.128.165	terpasang	terpasang	true			
.57 SLS30I483	HM2075	-	terpasang	-	false	03-06-2025		2025-06-03 09:06:47
58 SLS30I484	DT5664	10.187.128.75	terpasang	terpasang	true			
59 SLS30I485	LO160	10.187.128.164	terpasang	terpasang	true			
60 SLS30I486	WT200	10.187.128.167	terpasang	terpasang	true			
61 SLS30I487	LO148	10.187.128.162	terpasang	terpasang	true			
62 SLS30I488 63 SLS30I490	DT5896 DT5639	10.187.128.171 10.187.128.87	terpasang	terpasang	true			
64 SLS30I491	DT5897	10.187.128.87	terpasang terpasang	terpasang terpasang	true true			
65 SLS30I491	DT3785	10.187.128.170	terpasang	terpasang	true			
66 SLS30I492	FT297	10.187.128.168	terpasang	terpasang	true			
67 SLS30I524	DT5870	10.187.128.110	terpasang	terpasang	true			
68 SLS30I525	PM725	10.187.128.187	terpasang	terpasang	true			
69 SLS30I526	CT148	10.187.128.62	terpasang	terpasang	true	25-05-2025		
70 SLS30I527	DT5918	10.187.128.177	terpasang	terpasang	true			
71 SLS30I528	PM007	10.187.128.182	terpasang	terpasang	true			
72 SLS30I529	DT4120	10.187.128.140	terpasang	terpasang	true	02-06-2025	mh sering restart (pending harus replace)	2025-06-02 17:19:39
73 SLS30I530	LD3121	10.187.128.172	terpasang	terpasang	true			
74 SLS30I531	LD3123	10.187.128.174	terpasang	terpasang	true			
.75 SLS30I532	DT5900	10.187.128.163	terpasang	terpasang	true			
.76 SLS30I533	LD3122	10.187.128.173	terpasang	terpasang	true			
.84 SDLIR040	DT5665	10.187.128.30	terpasang	terpasang	true	27-04-2025		
.85 SLS30I191	HM2074		terpasang	-	false	03-06-2025	ip blum ada	2025-06-03 09:07:13
.87 SDLIR031	HM1732	10.187.128.210	terpasang	-	true	03-06-2025		2025-06-03 09:24:07
.88 SDLIR035	HM1820	10.187.128.209	terpasang	-	true	03-06-2025		2025-06-03 09:24:39
.89 SDLIR033	LD2015	10.187.128.24	terpasang	terpasang	true	27-04-2025		2025 06 00 12 44 00
.90 SLS30I001	LD3130	10.187.128.222	terpasang	-	true	09-06-2025		2025-06-09 13:44:09
91 SDLIR032 92 SLS30I489	LD832G HM2071	10.187.128.41 10.187.128.236	terpasang	terpasang	true	27-04-2025 11-06-2025		2025-06-11 15:29:37
93 SDLIR039	HM2071	10.167.126.230	terpasang	terpasang	true false	03-06-2025		2025-06-11 13.29.37
95 SDLIR028	LD2006	-	terpasang terpasang	- -	true	25-05-2025		2023-00-03 09.00.01
96 SDLIR043	HM2072	1-	terpasang	- -	false	03-06-2025		2025-06-03 09:04:53
97 SDLIR030	PM701	-	terpasang	-	true	25-05-2025		2025 00 05 03.04.55
98 SDLIR042	HM2073	-	terpasang	-	false	03-06-2025		2025-06-03 09:05:39
99 SDLIR026	PM702	-	terpasang	-	true	02-06-2025		122 23 22 33.33.33
00 SDLIR041	DT4024	10.187.128.34	terpasang	terpasang	true	25-05-2025		
06 SDLIR029	LD3124	10.187.128.211	terpasang	-	true	09-06-2025		2025-06-09 13:43:05
32 SLS30I152	DT4693	10.187.128.3	terpasang	terpasang	true	11-06-2025		2025-06-11 15:50:49
33 SLS30I535	LD3129	10.187.128.239	terpasang	terpasang	true	11-06-2025		2025-06-11 15:28:30
34 SLS30I536	NULL	NULL	standby	-	false			
35 SLS30I534	NULL	NULL	standby	-	false			
36 SLS30I537	NULL	NULL	standby	-	false			
37 SLS30I541	LD3125	10.187.128.235	terpasang	terpasang	true	11-06-2025		2025-06-11 15:27:49
38 SLS30I542	LD3132	10.187.128.232	terpasang	terpasang	false	11-06-2025		2025-06-11 15:30:59
39 SLS30I540	NULL	NULL	standby	-	false	11.06.2225		2025 20 11 15 22 10
40 SLS30I543	LD3128	10.187.128.238	terpasang	terpasang	true	11-06-2025		2025-06-11 15:28:16
41 SLS30I539	LD3131	10.187.128.231	terpasang	terpasang	true	11-06-2025		2025-06-11 15:26:43
42 SLS30I538	NULL	NULL	standby	-	false	25 05 2025		
43 SLS30I309	HM1786	10 107 120 107	terpasang	torpacana	true	25-05-2025		2025 06 11 15:47:14
44 SDLIR013	DT4285	10.187.128.197	terpasang	terpasang	true	11-06-2025		2025-06-11 15:47:14
45 SDLIR037	DT4404	10.187.128.207	terpasang	terpasang	true	11-06-2025		2025-06-11 15:53:46
46 SLS30I113 47 SLS30I198	DT4371 DT4723	10.187.128.198	terpasang	terpasang	true	11-06-2025 11-06-2025		2025-06-11 15:49:52
47 SLS301198 48 SDLIR036	FT304	10.187.128.116 10.187.128.208	terpasang	terpasang	true	09-06-2025		2025-06-11 15:51:51 2025-06-09 14:10:11
49 SLS301015	LD784	10.107.120.208	terpasang	terpasang	truo	25-05-2025 3/4		2025-00-09 14:10:11
+9 3E3301013	LD / 04	-	terpasang		tiue	43-03-2023		Jun 18, 2025 a

Jun 18, 2025 at 02:33 PM

Database: devgodmy_mh02, Table: devices, Purpose: Dumping data

id	deviceid	unitno	deviceip	mh02status	modem_cpe	power	last_update	note	date_created
250 9	SLS30I016	LD782	-	terpasang	-	true	25-05-2025		
251 9	SLS30I052	LD783	10.187.128.124	terpasang	terpasang	true	15-06-2025		2025-06-15 23:05:43
252 9	SLS30I146	LD772	-	terpasang	-	true	25-05-2025		
253 9	SDLIR038	LD921	10.187.128.240	terpasang	terpasang	true	15-06-2025		2025-06-15 23:15:10
254 9	SLS30I150	TW240	-	terpasang	-	true	25-05-2025		