

# HitecApp Safety

## Desktop Lead Assessor & Engineering Manual

PT Safety Indonesia Utama · ATEX Assessment & Compliance Services

### Purpose of this Desktop Manual

This comprehensive guide provides technical instructions for Lead Safety Assessors and Compliance Engineers using HitecApp on Desktop & Laptop workstations. Master the 2-column studio layout, review high-resolution equipment photos, draw colored annotations & doodles, apply ATEX/IEC 60079 standards, and export final client reports.

### First Step: Set Up Your Project

**Important:** You must select an existing inspection or create a new project before uploading equipment photos or modifying captions.

#### Option A: Select Existing Project

1. Click the 'Select a project...' dropdown. 2. Choose your client plant project.  All photos uploaded by field surveyors load instantly.

#### Option B: Create New Project

1. Enter Company Name (e.g. PT Safety Indonesia Utama). 2. Enter City Name (e.g. Jakarta). 3. Type New Project Name. 4. Click '+ Create'.  Project is created and ready for batch uploads.

## Step 1: Log In & Desktop Mode Selection

*Secure engineer authentication with 1440px wide-screen workspace*

1. Open Google Chrome, Microsoft Edge, or Firefox on your desktop or laptop.
2. Select 'Desktop' mode radio button on the login screen.
3. Enter your certified assessor credentials (Email & Password).
4. Click the blue 'Sign In' button. Your active session is protected with auto-save and device validation.

### Pro Tip

Selecting Desktop mode automatically activates the side-by-side 2-column studio layout optimized for widescreen monitors.




Figure: Desktop Workspace Screen for Step 1

## Step 2: Desktop Two-Column Studio Overview

*Left Photo Queue (35%) & Right Carousel Studio (65%) for maximum productivity*

1. The desktop interface splits into two powerful functional panels:
2. Left Column (Photo Queue & Uploads): Displays your project selection, batch upload zone, photo count badges, and reorderable thumbnail queue.
3. Right Column (Carousel & Assessment Studio): Displays the high-resolution photo viewer, 5-row caption editor, and ATEX lead assessor observation fields.
4. Click any photo in the left queue to immediately open it in the right studio pane.

### 💡 Pro Tip

Use your keyboard Arrow Keys (Left / Right) to quickly flip through inspection photos in the Carousel Studio.




Figure: Desktop Workspace Screen for Step 2

### Step 3: Batch Upload Equipment Photos & Folders

Upload single files or whole directories with instant WebP/JPEG compression

1. In the left panel Upload Zone, click 'Choose Files' or drag-and-drop multiple image files.
2. To ingest an entire plant survey folder at once, click the 'Upload Folder' button.
3. Photos are compressed on the fly to maximize network speed while retaining crystal-clear nameplate text.
4. Each photo appears in the queue with a status badge: Queued → Uploading → Done ☒.

#### Pro Tip

You can upload up to 200 high-resolution equipment photos in a single batch without browser slowdown.




Figure: Desktop Workspace Screen for Step 3

## Step 4: Dual-Panel Workspace & Focus Navigation

Seamlessly inspect equipment photos side-by-side with inspection data

1. As photos finish uploading, they display with sequential row numbers (1., 2., 3...).
2. The active photo is highlighted with an emerald border and synchronized in the Right Carousel Studio.
3. Status pills indicate whether a photo has a complete caption (Green ☒) or requires assessor review (Yellow ☐).
4. Click 'Collapse Details ▲' in the header to maximize vertical workspace.

### 💡 Pro Tip

Hover over any thumbnail in the left queue to preview the filename, size, and quick caption summary.




Figure: Desktop Workspace Screen for Step 4

## Step 5: Visual Image Markup, Doodles & Color Selection

*Highlight hazardous zones, earthing studs, and enclosures with customizable colors*

1. Above the equipment photo, select from your engineering annotation tools: Rect (Rectangle), Arrow, Doodle (Free Draw), or Text.
2. Pick custom colors from the Color Picker palette (e.g. Red for Ex d junction box, Amber for Earthing terminals, Cyan for Cooling fins).
3. Adjust the Stroke Width slider (1px to 10px) to suit your report markup emphasis.
4. Click 'Save Image' to burn the annotations directly into the equipment photo for client inspection deliverables.

### Pro Tip

Use Red Rectangles to frame flameproof junction boxes and Amber Arrows to verify electrostatic bonding paths.




Figure: Desktop Workspace Screen for Step 5

## Step 6: Technical Captioning & Equipment Identification

*Precise nameplate specs, Zone classification, and tag numbering*

1. Click inside the Caption field below the photo canvas.
2. Enter the equipment tag, manufacturer, rating, and Zone location (e.g. 'TECO 3-Phase Induction Motor 2.2kW, 220/380V, 50Hz, IP55 - Zone 1 HAC Assessment & Earthing Inspection').
3. Click outside the field or tap the checkmark to save. Captions sync to cloud storage in real time.

### Pro Tip

Always include equipment certification details (e.g. Ex d IIB T4, IP rating) in the caption for compliance audit readiness.

The screenshot displays the HitecApp-Safety Desktop Workspace interface. The top navigation bar includes the Hitec logo, 'MONTHLY USAGE', '0 / 300 REPORTS', a 'Help' dropdown, a user profile 'demo@hitec.id' with 'BASIC' access, and a 'Logout' button. A status bar at the top left indicates '✓ Saved 29 seconds ago'.

The main workspace is divided into several sections:

- COMPANY:** 'PT Safety Indonesia Utama' and 'CITY: Jakarta'.
- PROJECT:** A dropdown menu showing 'Desktop QA Test' with a 'Create' button.
- Media Selection:** 'Select Folder' and 'Use Camera' buttons. Below, a list of photos shows '1 selected / 2 photos'.
- Photo Editor:** A large canvas displaying a photo of a TECO 3-phase induction motor. The photo has a red bounding box around the motor and blue arrows pointing to specific parts. The editor includes tools for 'Doodle', 'Arrow', 'Rect', 'Text', 'Undo', 'Clear', and a '3px' brush size slider. A 'Save Image' button is at the bottom left of the canvas.
- Form Fields:**
  - CAPTION:** 'ssessment & Earthing Inspection.'
  - DATE:** '27/08/2026'
  - LOCATION:** 'Site'
  - GRADES:** 'F1', 'F2' (selected), 'F3', 'F4'
  - STATUS:** 'Open' (with 'Close' button)
  - COMMENTS:** A text area with 'AI Assist: ON' and a 'Hold to Talk' button.
  - AI RECOMMENDATION:** A section with 'Auto' and 'Clear' buttons, containing suggestions like '+ Tamper seal and safety locking mechanism compromised, requiring immediate integrity verification.' and '+ Discharge hose elastomeric deterioration observed, increasing flow impedance.'
- Bottom Bar:** Includes 'Save (1)', 'PDF', 'PPT', 'DOC' buttons, a 'Regenerate' button, an 'Edit Manually' button, a language selector ('Bahasa', 'English'), and a 'Save Report' button.

Figure: Desktop Workspace Screen for Step 6

## Step 7: ATEX Assessor Observations & Risk Priority Grading

Comprehensive engineering assessment (IEC 60079 & EN 1127-1 compliance)

1. Document ignition risk observations and corrective recommendations in the dedicated engineering textfields.
2. Assign Risk Priority Grades (F1 Red = Immediate Hazard, F2 Orange = High Priority, F3 Yellow = Moderate, F4 Green = Minor / Conforming).
3. Toggle Latest Status between 'Open' (Action Required) and 'Close' (Mitigated).
4. Assessments are automatically linked to the specific equipment photo and included in the exported report.

### Pro Tip

Reference relevant European and International standards (e.g. IEC 60079-14 Section 9, EN 1127-1) directly in your recommendations.

The screenshot displays the Desktop Workspace Screen for Step 7, titled "DESKTOP\_QA\_TEST\_2026-0...". The interface is divided into several sections:

- Header:** Includes "MONTHLY USAGE", "0 / 300 REPORTS", a "Help" dropdown, a user profile "demo@hitec.id" with "BASIC" access, and a "Logout" button.
- Left Panel:**
  - COMPANY:** "PT Safety Indonesia Utama", **CITY:** "Jakarta".
  - PROJECT:** "Desktop QA Test" (with a dropdown menu).
  - Media:** "Select Folder" and "Use Camera" buttons.
  - Image Gallery:** Shows two selected images: "desktop\_qa\_test\_2026-08-27-001.jpg" and "desktop\_qa\_test\_2026-08-27-002.jpg". Each image has a "MIC" icon and a "No caption (click to expand editor)" note.
  - Bottom Bar:** "Save (1)", "PDF", "PPT", and "DOC" export options.
- Right Panel:**
  - Image Editor:** Features "Doodle", "Arrow", "Rect", "Text", "Undo", "Clear", and "3px" brush size controls. A "Save Image" button is present.
  - Image:** A photograph of a "TECO 3-Phase Induction Motor" with a red bounding box and a blue arrow pointing to it.
  - Metadata:** "CAPTION: TECO 3-Phase Induction Motor (2)", "DATE: 27/08/2026", "LOCATION: Site".
  - Grades:** "GRADES: F1 F2 F3 F4" (with F1 highlighted in red).
  - Status:** "STATUS: Open Close" (with "Open" highlighted in green).
  - Comments:** "COMMENTS: AI Assist: ON" (with "Hold to Talk" and "Clear" buttons). A text area for "Write observation comments..." is provided.
  - Suggestions:**
    - "+ Suggestions: + Tamper seal and safety locking mechanism compromised, requiring immediate integrity verification."
    - "+ Discharge hose elastomeric deterioration observed, increasing flow impedance."
  - AI Recommendation:** "AI RECOMMENDATION: Auto" (with "Clear" button). A text area for "Mitigation recommendation actions..." is provided.
  - Bottom Bar:** "Regenerate", "Edit Manually", "Bahasa", "English", and "Save Report" buttons.

Figure: Desktop Workspace Screen for Step 7

## Step 8: Drag-and-Drop Photo Sequence Management

*Group inspection findings into logical plant report sequences*

1. To change the order of photos in your final report, hover over the 6-dot grip handle (:::) on the left queue row.
2. Click and drag the row up or down to its new target position.
3. Release your mouse. The entire queue rennumbers automatically (1., 2., 3...).
4. The reordered sequence is instantly reflected in all generated PDF, PowerPoint, and Word documents.

### 💡 Pro Tip

Group photos by process area or equipment skid (e.g. Overview first, followed by Nameplate close-up and Terminal Box).




Figure: Desktop Workspace Screen for Step 8

## Step 9: Save & View-Only Inspection Lock

Freeze review state and verify final findings before client delivery

1. When you finish captioning and assessing photos, click 'Save' on the bottom action bar.
2. The workspace transitions into View Mode (all editing inputs are locked to prevent inadvertent keystrokes).
3. The Save button converts into an 'Edit' toggle.
4. Click 'Edit' anytime you need to add more photos or revise engineering observations.

### Pro Tip

Switch to View Mode before presenting inspection findings in client review meetings to ensure data safety.




Figure: Desktop Workspace Screen for Step 9

## Step 10: Multi-Format Report Generation (PDF, PPT, Word)

Export audit-ready ATEX deliverables in 1 click

1. From the bottom PublishBar, select your desired export format:
2.  Word (.docx): Generates a fully formatted, high-contrast engineering document ready for official client submission.
3.  PowerPoint (.pptx): Creates presentation slides with side-by-side equipment photos and bulleted assessor findings.
4.  PDF (.pdf): Produces a clean, tamper-evident inspection report ideal for email distribution and archiving.
5. Exports download directly to your computer's Downloads folder within seconds.

### Pro Tip

Exported Word documents retain all formatting and typography rules (!font16) established by PT Safety Indonesia Utama.




Figure: Desktop Workspace Screen for Step 10