



VG
Dr Sim Siang Kok




Sectional Front View A-A



Plan View


Need construction lines joining the 3 views.

??? The drawing is on 3 separate pieces of A4 paper, how to draw the construction lines? This makes no sense and should be fine to ignore.



Right View

Part List		
Part No	Name	Qty
1	Housing	1
2	Shaft	1
3	Profile Key	1
4	Key Lock Screw	1
5	Spur Gear	1
6	Ball Bearing	1
7	Bearing Lock Washer	1
8	Bearing Lock Nut	1
9	Bearing Retainer Cap	1
10	Hex Head Cap Screw	8
11	Retaining Ring	2



Place retaining rings on both the left and right side of the gear.

Part list for retaining rings

??? Already included in the part list above. Safe to ignore.