

Last day's daily report

Hardware	● Add all footprints, models, and PCB work to git
firmwear	● Made some changes in code and added ROS nodes for the firmwear side
softwear	● Finished all documentation needed and the technical report ● Finished connection with ROS and adding nodes to publish and receive