

Summary Report

Site: DE46-M138

Cable Label	Limit	Result	Length (m)	Margin (dB)	Date & Time
MPO #1122	200GBASE-SR10	✓	-	-	29-01-2026 01:43:17 PM
MPO #1123	200GBASE-SR10	✓	-	-	29-01-2026 01:42:47 PM
MPO #1124	200GBASE-SR10	✓	-	-	29-01-2026 01:42:16 PM
MPO #1125	200GBASE-SR10	✓	-	-	29-01-2026 01:41:35 PM
MPO #1126	200GBASE-SR10	✓	-	-	29-01-2026 01:40:52 PM
MPO #1127	200GBASE-SR10	✓	-	-	29-01-2026 01:40:27 PM
MPO #1128	200GBASE-SR10	✓	-	-	29-01-2026 01:40:05 PM
MPO #1129	200GBASE-SR10	✓	-	-	29-01-2026 01:39:31 PM
MPO #1130	200GBASE-SR10	✓	-	-	29-01-2026 01:38:40 PM
MPO #1131	200GBASE-SR10	✓	-	-	29-01-2026 01:38:07 PM
MPO #1132	200GBASE-SR10	✓	-	-	29-01-2026 01:37:34 PM
MPO #1133	200GBASE-SR10	✓	-	-	29-01-2026 01:36:46 PM
MPO #1134	200GBASE-SR10	✓	-	-	29-01-2026 01:36:04 PM
MPO #1135	200GBASE-SR10	✓	-	-	29-01-2026 01:35:28 PM
MPO #1136	200GBASE-SR10	✓	-	-	29-01-2026 01:34:51 PM
MPO #1137	200GBASE-SR10	✓	-	-	29-01-2026 01:34:23 PM
MPO #1138	200GBASE-SR10	✓	-	-	29-01-2026 01:34:01 PM
MPO #1139	200GBASE-SR10	✓	-	-	29-01-2026 01:33:33 PM
MPO #1140	200GBASE-SR10	✓	-	-	29-01-2026 01:32:48 PM
MPO #1141	200GBASE-SR10	✓	-	-	29-01-2026 01:32:22 PM
MPO #1142	200GBASE-SR10	✓	-	-	29-01-2026 01:32:03 PM
MPO #1143	200GBASE-SR10	✓	-	-	29-01-2026 01:31:38 PM
MPO #1144	200GBASE-SR10	✓	-	-	29-01-2026 01:31:10 PM
MPO #1145	200GBASE-SR10	✓	-	-	29-01-2026 01:30:51 PM
MPO #1146	200GBASE-SR10	✓	-	-	29-01-2026 01:30:29 PM
MPO #1147	200GBASE-SR10	✓	-	-	29-01-2026 01:29:57 PM
MPO #1148	200GBASE-SR10	✓	-	-	29-01-2026 01:29:18 PM
MPO #1149	200GBASE-SR10	✓	-	-	29-01-2026 01:28:50 PM
MPO #1150	200GBASE-SR10	✓	-	-	29-01-2026 01:28:25 PM
MPO #1151	200GBASE-SR10	✓	-	-	29-01-2026 01:27:25 PM
MPO #1152	200GBASE-SR10	✓	-	-	29-01-2026 01:25:32 PM
MPO #1153	200GBASE-SR10	✓	-	-	29-01-2026 01:25:01 PM
MPO #1154	200GBASE-SR10	✓	-	-	29-01-2026 01:23:47 PM
MPO #1155	200GBASE-SR10	✓	-	-	29-01-2026 01:23:23 PM
MPO #1156	200GBASE-SR10	✓	-	-	29-01-2026 01:23:05 PM
MPO #1157	200GBASE-SR10	✓	-	-	29-01-2026 01:22:46 PM
MPO #1158	200GBASE-SR10	✓	-	-	29-01-2026 01:22:27 PM
MPO #1159	200GBASE-SR10	✓	-	-	29-01-2026 01:22:04 PM
MPO #1160	200GBASE-SR10	✓	-	-	29-01-2026 01:21:30 PM
MPO #1161	200GBASE-SR10	✓	-	-	29-01-2026 01:20:39 PM
MPO #1162	200GBASE-SR10	✓	-	-	29-01-2026 01:18:40 PM
MPO #1163	200GBASE-SR10	✓	-	-	29-01-2026 01:18:15 PM
MPO #1164	200GBASE-SR10	✓	-	-	29-01-2026 01:17:49 PM
MPO #1165	200GBASE-SR10	✓	-	-	29-01-2026 01:17:10 PM
MPO #1166	200GBASE-SR10	✓	-	-	29-01-2026 01:16:25 PM
MPO #1167	200GBASE-SR10	✓	-	-	29-01-2026 01:16:06 PM
MPO #1168	200GBASE-SR10	✓	-	-	29-01-2026 01:15:38 PM
MPO #1169	200GBASE-SR10	✓	-	-	29-01-2026 01:15:11 PM

Summary Report

Cable Label	Limit	Result	Length (m)	Margin (dB)	Date & Time
MPO #1170	200GBASE-SR10	✓	-	-	29-01-2026 01:12:57 PM
MPO #1171	200GBASE-SR10	✓	-	-	29-01-2026 01:12:28 PM
MPO #1172	200GBASE-SR10	✓	-	-	29-01-2026 01:12:02 PM
MPO #1173	200GBASE-SR10	✓	-	-	29-01-2026 01:11:41 PM
MPO #1174	200GBASE-SR10	✓	-	-	29-01-2026 01:11:11 PM
MPO #1175	200GBASE-SR10	✓	-	-	29-01-2026 01:10:34 PM
MPO #1176	200GBASE-SR10	✓	-	-	29-01-2026 01:10:12 PM
MPO #1177	200GBASE-SR10	✓	-	-	29-01-2026 01:09:45 PM
MPO #1178	200GBASE-SR10	✓	-	-	29-01-2026 01:09:13 PM
MPO #1179	200GBASE-SR10	✓	-	-	29-01-2026 01:08:33 PM
MPO #1180	200GBASE-SR10	✓	-	-	29-01-2026 11:54:32 AM
MPO #1181	200GBASE-SR10	✓	-	-	29-01-2026 11:54:09 AM
MPO #1182	200GBASE-SR10	✓	-	-	29-01-2026 11:53:33 AM
MPO #1183	200GBASE-SR10	✓	-	-	29-01-2026 11:53:11 AM
MPO #1184	200GBASE-SR10	✓	-	-	29-01-2026 11:52:35 AM
MPO #1185	200GBASE-SR10	✓	-	-	29-01-2026 11:51:05 AM
MPO #1186	200GBASE-SR10	✓	-	-	29-01-2026 11:50:45 AM
MPO #1187	200GBASE-SR10	✓	-	-	29-01-2026 11:50:31 AM
MPO #1188	200GBASE-SR10	✓	-	-	29-01-2026 11:49:50 AM
MPO #1189	200GBASE-SR10	✓	-	-	29-01-2026 11:49:13 AM
MPO #1190	200GBASE-SR10	✓	-	-	29-01-2026 11:48:37 AM
MPO #1191	200GBASE-SR10	✓	-	-	29-01-2026 11:48:22 AM
MPO #1192	200GBASE-SR10	✓	-	-	29-01-2026 11:47:59 AM
MPO #1193	200GBASE-SR10	✓	-	-	29-01-2026 11:46:42 AM
MPO #1194	200GBASE-SR10	✓	-	-	29-01-2026 11:45:38 AM
MPO #1195	200GBASE-SR10	✓	-	-	29-01-2026 11:44:58 AM
MPO #1196	200GBASE-SR10	✓	-	-	29-01-2026 11:44:30 AM
MPO #1197	200GBASE-SR10	✓	-	-	29-01-2026 11:43:46 AM
MPO #1198	200GBASE-SR10	✓	-	-	29-01-2026 11:42:53 AM
MPO #1199	200GBASE-SR10	✓	-	-	29-01-2026 11:42:16 AM
MPO #1200	200GBASE-SR10	✓	-	-	29-01-2026 11:41:57 AM
MPO #1201	200GBASE-SR10	✓	-	-	29-01-2026 11:41:06 AM
MPO #1202	200GBASE-SR10	✓	-	-	29-01-2026 11:39:35 AM
MPO #1203	200GBASE-SR10	✓	-	-	29-01-2026 11:38:23 AM
MPO #1204	200GBASE-SR10	✓	-	-	29-01-2026 11:38:02 AM
MPO #1205	200GBASE-SR10	✓	-	-	29-01-2026 11:36:01 AM
MPO #1206	200GBASE-SR10	✓	-	-	29-01-2026 11:35:02 AM
MPO #1207	200GBASE-SR10	✓	-	-	29-01-2026 11:34:42 AM
MPO #1208	200GBASE-SR10	✓	-	-	29-01-2026 11:34:17 AM
MPO #1209	200GBASE-SR10	✓	-	-	29-01-2026 11:33:38 AM
MPO #1210	200GBASE-SR10	✓	-	-	29-01-2026 11:33:09 AM
MPO #1211	200GBASE-SR10	✓	-	-	29-01-2026 11:32:39 AM
MPO #1212	200GBASE-SR10	✓	-	-	29-01-2026 11:31:49 AM
MPO #1213	200GBASE-SR10	✓	-	-	29-01-2026 11:31:01 AM
MPO #1214	200GBASE-SR10	✓	-	-	29-01-2026 11:30:29 AM
MPO #1215	200GBASE-SR10	✓	-	-	29-01-2026 11:30:04 AM
MPO #1216	200GBASE-SR10	✓	-	-	29-01-2026 11:29:36 AM
MPO #1217	200GBASE-SR10	✓	-	-	29-01-2026 11:29:04 AM

Summary Report

Cable Label	Limit	Result	Length (m)	Margin (dB)	Date & Time
MPO #1218	200GBASE-SR10	✓	-	-	29-01-2026 11:27:58 AM
MPO #1219	200GBASE-SR10	✓	-	-	29-01-2026 11:27:31 AM
MPO #1220	200GBASE-SR10	✓	-	-	29-01-2026 11:26:36 AM
MPO #1221	200GBASE-SR10	✓	-	-	29-01-2026 11:26:10 AM
MPO #1222	200GBASE-SR10	✓	-	-	29-01-2026 11:25:50 AM
MPO #1223	200GBASE-SR10	✓	-	-	29-01-2026 11:25:18 AM
MPO #1224	200GBASE-SR10	✓	-	-	29-01-2026 11:24:46 AM
MPO #1225	200GBASE-SR10	✓	-	-	29-01-2026 11:24:12 AM
MPO #1226	200GBASE-SR10	✓	-	-	29-01-2026 11:23:47 AM
MPO #1227	200GBASE-SR10	✓	-	-	29-01-2026 11:23:23 AM
MPO #1228	200GBASE-SR10	✓	-	-	29-01-2026 11:22:37 AM
MPO #1229	200GBASE-SR10	✓	-	-	29-01-2026 11:21:56 AM
MPO #1230	200GBASE-SR10	✓	-	-	29-01-2026 11:21:13 AM
MPO #1231	200GBASE-SR10	✓	-	-	29-01-2026 11:20:31 AM
MPO #1232	200GBASE-SR10	✓	-	-	29-01-2026 11:20:07 AM
MPO #1233	200GBASE-SR10	✓	-	-	29-01-2026 11:19:44 AM
MPO #1234	200GBASE-SR10	✓	-	-	29-01-2026 11:18:23 AM
MPO #1235	200GBASE-SR10	✓	-	-	29-01-2026 11:17:41 AM
MPO #1236	200GBASE-SR10	✓	-	-	29-01-2026 11:17:16 AM
MPO #1237	200GBASE-SR10	✓	-	-	29-01-2026 11:17:04 AM
MPO #1238	200GBASE-SR10	✓	-	-	29-01-2026 11:16:22 AM
MPO #1239	200GBASE-SR10	✓	-	-	29-01-2026 11:15:42 AM
MPO #1240	200GBASE-SR10	✓	-	-	29-01-2026 11:14:49 AM
MPO #1241	200GBASE-SR10	✓	-	-	29-01-2026 11:14:12 AM
MPO #1242	200GBASE-SR10	✓	-	-	29-01-2026 11:13:06 AM
MPO #1243	200GBASE-SR10	✓	-	-	29-01-2026 11:12:41 AM
MPO #1244	200GBASE-SR10	✓	-	-	29-01-2026 11:12:33 AM
MPO #1245	200GBASE-SR10	✓	-	-	29-01-2026 11:11:34 AM
MPO #1246	200GBASE-SR10	✓	-	-	29-01-2026 11:10:40 AM
MPO #1247	200GBASE-SR10	✓	-	-	29-01-2026 11:10:14 AM
MPO #1248	200GBASE-SR10	✓	-	-	29-01-2026 11:09:48 AM
MPO #1249	200GBASE-SR10	✓	-	-	29-01-2026 11:07:18 AM
MPO #1250	200GBASE-SR10	✓	-	-	29-01-2026 11:06:52 AM
MPO #1251	200GBASE-SR10	✓	-	-	29-01-2026 11:06:26 AM
MPO #1252	200GBASE-SR10	✓	-	-	29-01-2026 11:04:11 AM
MPO #1253	200GBASE-SR10	✓	-	-	29-01-2026 11:03:05 AM
MPO #1254	200GBASE-SR10	✓	-	-	29-01-2026 10:58:46 AM
MPO #1255	200GBASE-SR10	✓	-	-	29-01-2026 10:58:27 AM
MPO #1256	200GBASE-SR10	✓	-	-	29-01-2026 10:57:47 AM
MPO #1257	200GBASE-SR10	✓	-	-	29-01-2026 10:56:24 AM
MPO #1258	200GBASE-SR10	✓	-	-	29-01-2026 10:55:58 AM
MPO #1259	200GBASE-SR10	✓	-	-	29-01-2026 10:55:40 AM
MPO #1260	200GBASE-SR10	✓	-	-	29-01-2026 10:54:46 AM
MPO #1261	200GBASE-SR10	✓	-	-	29-01-2026 10:54:15 AM
MPO #1262	200GBASE-SR10	✓	-	-	29-01-2026 10:53:52 AM
MPO #1263	200GBASE-SR10	✓	-	-	29-01-2026 10:53:30 AM
MPO #1264	200GBASE-SR10	✓	-	-	29-01-2026 10:53:08 AM
MPO #1265	200GBASE-SR10	✓	-	-	29-01-2026 10:52:34 AM

Summary Report

Cable Label	Limit	Result	Length (m)	Margin (dB)	Date & Time
MPO #1266	200GBASE-SR10	✓	-	-	29-01-2026 10:52:06 AM
MPO #1267	200GBASE-SR10	✓	-	-	29-01-2026 10:51:33 AM
MPO #1268	200GBASE-SR10	✓	-	-	29-01-2026 10:51:11 AM
MPO #1269	200GBASE-SR10	✓	-	-	29-01-2026 10:50:48 AM
MPO #1270	200GBASE-SR10	✓	-	-	29-01-2026 10:50:15 AM
MPO #1271	200GBASE-SR10	✓	-	-	29-01-2026 10:49:52 AM
MPO #1272	200GBASE-SR10	✓	-	-	29-01-2026 10:49:21 AM
MPO #1273	200GBASE-SR10	✓	-	-	29-01-2026 10:48:59 AM
MPO #1274	200GBASE-SR10	✓	-	-	29-01-2026 10:47:34 AM
MPO #1275	200GBASE-SR10	✓	-	-	29-01-2026 10:47:09 AM
MPO #1276	200GBASE-SR10	✓	-	-	29-01-2026 10:46:52 AM
MPO #1277	200GBASE-SR10	✓	-	-	29-01-2026 10:46:27 AM
MPO #1278	200GBASE-SR10	✓	-	-	29-01-2026 10:46:10 AM
MPO #1279	200GBASE-SR10	✓	-	-	29-01-2026 10:45:43 AM
MPO #1280	200GBASE-SR10	✓	-	-	29-01-2026 10:45:09 AM
MPO #1281	200GBASE-SR10	✓	-	-	29-01-2026 10:44:37 AM
MPO #1282	200GBASE-SR10	✓	-	-	29-01-2026 10:42:21 AM
MPO #1283	200GBASE-SR10	✓	-	-	29-01-2026 10:42:11 AM
MPO #1284	200GBASE-SR10	✓	-	-	29-01-2026 10:41:31 AM
MPO #1285	200GBASE-SR10	✓	-	-	29-01-2026 10:41:04 AM
MPO #1286	200GBASE-SR10	✓	-	-	29-01-2026 10:40:07 AM
MPO #1287	200GBASE-SR10	✓	-	-	29-01-2026 10:39:33 AM
MPO #1288	200GBASE-SR10	✓	-	-	29-01-2026 10:38:42 AM
MPO #1289	200GBASE-SR10	✓	-	-	29-01-2026 10:37:54 AM
MPO #1290	200GBASE-SR10	✓	-	-	29-01-2026 10:37:18 AM
MPO #1291	200GBASE-SR10	✓	-	-	29-01-2026 10:36:14 AM
MPO #1292	200GBASE-SR10	✓	-	-	29-01-2026 10:35:35 AM
MPO #1293	200GBASE-SR10	✓	-	-	29-01-2026 10:34:50 AM
MPO #1294	200GBASE-SR10	✓	-	-	29-01-2026 10:34:25 AM
MPO #1295	200GBASE-SR10	✓	-	-	29-01-2026 10:33:13 AM
MPO #1296	200GBASE-SR10	✓	-	-	29-01-2026 10:32:25 AM
MPO #1297	200GBASE-SR10	✓	-	-	29-01-2026 10:31:57 AM
MPO #1298	200GBASE-SR10	✓	-	-	29-01-2026 10:31:18 AM
MPO #1299	200GBASE-SR10	✓	-	-	29-01-2026 10:30:28 AM
MPO #1300	200GBASE-SR10	✓	-	-	29-01-2026 10:29:03 AM
MPO #1301	200GBASE-SR10	✓	-	-	29-01-2026 10:26:57 AM
MPO #1302	200GBASE-SR10	✓	-	-	29-01-2026 10:26:26 AM
MPO #1303	200GBASE-SR10	✓	-	-	29-01-2026 10:25:30 AM
MPO #1304	200GBASE-SR10	✓	-	-	29-01-2026 10:24:31 AM
MPO #1305	200GBASE-SR10	✓	-	-	29-01-2026 10:23:55 AM
MPO #1306	200GBASE-SR10	✓	-	-	29-01-2026 10:23:13 AM
MPO #1307	200GBASE-SR10	✓	-	-	29-01-2026 10:22:32 AM
MPO #1308	200GBASE-SR10	✓	-	-	29-01-2026 10:22:06 AM
MPO #1309	200GBASE-SR10	✓	-	-	29-01-2026 10:21:13 AM
MPO #1310	200GBASE-SR10	✓	-	-	29-01-2026 10:20:31 AM
MPO #1311	200GBASE-SR10	✓	-	-	29-01-2026 10:20:08 AM
MPO #1312	200GBASE-SR10	✓	-	-	29-01-2026 10:19:24 AM
MPO #1313	200GBASE-SR10	✓	-	-	29-01-2026 10:19:02 AM

Summary Report

Cable Label	Limit	Result	Length (m)	Margin (dB)	Date & Time
MPO #1314	200GBASE-SR10	✓	-	-	29-01-2026 10:17:44 AM
MPO #1315	200GBASE-SR10	✓	-	-	29-01-2026 10:17:18 AM
MPO #1316	200GBASE-SR10	✓	-	-	29-01-2026 10:15:28 AM
MPO #1317	200GBASE-SR10	✓	-	-	29-01-2026 10:15:08 AM
MPO #1318	200GBASE-SR10	✓	-	-	29-01-2026 10:14:23 AM
MPO #1319	200GBASE-SR10	✓	-	-	29-01-2026 10:13:52 AM
MPO #1320	200GBASE-SR10	✓	-	-	29-01-2026 10:13:12 AM
MPO #1321	200GBASE-SR10	✓	-	-	29-01-2026 09:55:23 AM
MPO #1322	200GBASE-SR10	✓	-	-	29-01-2026 09:53:38 AM
MPO #1323	200GBASE-SR10	✓	-	-	29-01-2026 09:53:24 AM
MPO #1324	200GBASE-SR10	✓	-	-	29-01-2026 09:53:05 AM
MPO #1325	200GBASE-SR10	✓	-	-	29-01-2026 09:52:39 AM
MPO #1326	200GBASE-SR10	✓	-	-	29-01-2026 09:51:55 AM
MPO #1327	200GBASE-SR10	✓	-	-	29-01-2026 09:51:27 AM
MPO #1328	200GBASE-SR10	✓	-	-	29-01-2026 09:50:53 AM
MPO #1329	200GBASE-SR10	✓	-	-	29-01-2026 09:50:30 AM
MPO #1330	200GBASE-SR10	✓	-	-	29-01-2026 09:50:08 AM
MPO #1331	200GBASE-SR10	✓	-	-	29-01-2026 09:49:46 AM
MPO #1332	200GBASE-SR10	✓	-	-	29-01-2026 09:49:35 AM
MPO #1333	200GBASE-SR10	✓	-	-	29-01-2026 09:48:22 AM
MPO #1334	200GBASE-SR10	✓	-	-	29-01-2026 09:48:00 AM
MPO #1335	200GBASE-SR10	✓	-	-	29-01-2026 09:47:28 AM
MPO #1336	200GBASE-SR10	✓	-	-	29-01-2026 09:47:03 AM
MPO #1337	200GBASE-SR10	✓	-	-	29-01-2026 09:46:38 AM
MPO #1338	200GBASE-SR10	✓	-	-	29-01-2026 09:46:16 AM
MPO #1339	200GBASE-SR10	✓	-	-	29-01-2026 09:45:48 AM
MPO #1340	200GBASE-SR10	✓	-	-	29-01-2026 09:44:37 AM
MPO #1341	200GBASE-SR10	✓	-	-	29-01-2026 09:44:19 AM
MPO #1342	200GBASE-SR10	✓	-	-	29-01-2026 09:43:55 AM
MPO #1343	200GBASE-SR10	✓	-	-	29-01-2026 09:43:27 AM
MPO #1344	200GBASE-SR10	✓	-	-	29-01-2026 09:42:55 AM
MPO #1345	200GBASE-SR10	✓	-	-	29-01-2026 09:42:30 AM
MPO #1346	200GBASE-SR10	✓	-	-	29-01-2026 09:41:57 AM
MPO #1347	200GBASE-SR10	✓	-	-	29-01-2026 09:41:17 AM
MPO #1348	200GBASE-SR10	✓	-	-	29-01-2026 09:40:19 AM
MPO #1349	200GBASE-SR10	✓	-	-	29-01-2026 09:40:05 AM
MPO #1350	200GBASE-SR10	✓	-	-	29-01-2026 09:37:42 AM
MPO #1351	200GBASE-SR10	✓	-	-	29-01-2026 09:37:06 AM
MPO #1352	200GBASE-SR10	✓	-	-	29-01-2026 09:35:30 AM
MPO #1353	200GBASE-SR10	✓	-	-	29-01-2026 09:34:50 AM
MPO #1354	200GBASE-SR10	✓	-	-	29-01-2026 09:11:45 AM
MPO #1355	200GBASE-SR10	✓	-	-	29-01-2026 09:10:34 AM
MPO #1356	200GBASE-SR10	✓	-	-	29-01-2026 09:09:35 AM
MPO #1357	200GBASE-SR10	✓	-	-	29-01-2026 09:09:13 AM
MPO #1358	200GBASE-SR10	✓	-	-	29-01-2026 09:08:48 AM
MPO #1359	200GBASE-SR10	✓	-	-	29-01-2026 09:08:12 AM
MPO #1360	200GBASE-SR10	✓	-	-	29-01-2026 09:07:23 AM
MPO #1361	200GBASE-SR10	✓	-	-	29-01-2026 09:05:05 AM

Summary Report



Total for Site: DE46-M138	Pass	Fail	Length (m)
 MPO	240	0	0

Total for Selected Reports	Pass	Fail	Length (m)
 MPO	240	0	0