

Fire Safety Inspection Report

Addu Equatorial Hospital

Document version	2026
Record type	Demonstration operational document
Status	Controlled copy

Inspection scope

Emergency exits, alarm panels, extinguishers, hydrants, generator rooms, oxygen storage, and staff response records.

Overall finding

Substantially compliant. Two corrective actions require monitoring through the equipment-fault workflow.

Corrective actions

Replace two expired extinguishers and improve access clearance around the secondary electrical panel.

Follow-up

Facilities management will confirm closure within 30 days and attach photographic evidence.

Demo record - replace with the approved facility document before production use.