

Provisions and Use of Work Equipment Regulation

Inspection carried out under the Provisions and Use of Work Equipment (PUWER) Regulations 1998



Overview						
Inspect N	88969	Page:	1/1			
Job No	16944					
Customer	AECOM					
Contact	Michael William		Date	03/10/2024		
Tel	01293 72180	00				

Site	
CRAWLEY RTW	
PRIESTLEY WAY	
CRAWLEY	
RH10 9NT	

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000152256	Door Powered Vertical		0000152256

Asset Photograph				
Capture photograph of Asset, including asset number	See Photo 1			
Hazard Priority and Findings				
Intolerable - Defects requiring immediate action	None			
Substantial - Defects requiring attention within a time period	None			
Moderate - Other defects requiring attention	The travel of the leading edge of the door within floor guide is compromised causing operation to stop when opening.			
Tolerable - Observations	None			



General Comments		
None		

Engineer

Carmelo Belfiore

Industrial Safety Inspections Ltd 22-23 Amber Business Village

Amington Tamworth Staffordshire B77 4RP Tel: +44 (0) 1675 481779

Email: info@isisafety.com Web: www.isisafety.com

