

Provisions and Use of Work Equipment Regulation

Inspection carried out under the Provisions and Use of Work Equipment (PUWER) Regulations 1998



Overview					
Inspect N	34775	Page:		1/1	
Job No	12332				
Customer	AECOM				
Contact			Dat	te	26/01/2024
Tel					·

Site
ROTHERHAM DO/OFF
MAIN STREET
ROTHERHAM
S60 1AA

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
RM090124386	Turnstile Access		A41TURNSTILE01

Asset Photograph					
Capture photograph of Asset, including asset number	See Photo 1				
Hazard Priority and Findings					
Intolerable - Defects requiring immediate action	None				
Substantial - Defects requiring attention within a time period	None				
Moderate - Other defects requiring attention	signs of heavy corrosion at the base of the turnstile this is to be attended to and rectified to prevent further deterioration				
Tolerable - Observations	None				



General Comments		
None		

Engineer

Danny Earl

Industrial Safety Inspections Ltd 22-23 Amber Business Village

Amington Tamworth Staffordshire B77 4RP Tel: +44 (0) 1675 481779

Email: info@isisafety.com Web: www.isisafety.com

