## **Purchase Order**

Brigham Young University BRIGHAM YOUNG UNIVERSITY

BRIĞHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000014738 PROTECH ELECTRONICS\* 9486 S UNION SQUARE SANDY UT 84070

Dispatch via Print

Purchase Order	Da	te	Revision	Page
BYU-0000038647	05	/12/1999	9 2 - 05/12/	1999 1
Payment Terms	Freight Terms			Ship Via
NET 30	FOB Origin,	Buyer E	Bears Frt.	BYU
				Courier
Buyer	Phone/Email			Currency
Whitney, Kristina R.			USD	

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

**United States** 

 Tax Exempt?
 Y
 Tax Exempt ID:
 N10020
 Replenishment Option:
 Standard

 Line-Sch Item/Description
 Mfg ID
 Quantity UOM
 PO Price
 Extended Amt
 Due Date

1- 1 REPAIR ILN CANON CAMCORDER S/N 2060040323

1.00EA 2

220.00 0.00 CLOSED

**Schedule Total** 

0.00

PROBLEM: LOAD BASKET JAMES IN LOAD AND UNLOAD WITH CASSETTE IN. INCLUDE P/M

Item Total 0.00

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING

TO BE PICKED UP BY THE BYU COURIER SERVICE. PLEASE CALL (801) 378-4835 WHEN MATERIAL IS READY FOR PICK-UP.

**CHANGE ORDER #1** 

PUT PRICE INTO SYSTEM TO REFLECT THE ESTIMATE GIVEN BY VENDOR. \$140 O.K. TO PAY PER STEVE ZOBELL. 5/6/99 KRW

CHANGE ORDER #2

PRICE ADJUSTED FROM ORIGINAL ESTIMATE OF \$140 TO \$220. VENDOR FOUND SAND AND SALT WATER IN THE CAMCORDER WHICH WILL REQUIRE FURTHER REPAIRS. NEW ESTIMATE O.K.T O PAY PER STEVE ZOBELL OF ITSERVICES. 5/12/99 KRW

NOTIFIED VERN TO HAVE COURIER PICK UNIT UP FROM PROTECH. 5/20/99 KRW

Total PO Amount 0.00