Purchase Order

Brigham Young University BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000012080 ACCO USA* 32-00 SKILLMAN AVE LONG ISLAND CITY NY 11101

Dispatch via Print **Purchase Order** Date Revision Page 05/24/1999 BYU-0000039560 **Payment Terms Freight Terms** Ship Via NET 30 FOB Origin, Buyer Bears Frt. UPS Ground **Buyer** Phone/Email Currency

USD

0.00

Whitney, Kristina R.

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exem	pt? Y Tax Exempt ID: N10020		Replenishment C	ption: Standard		
Line-Sch	Item/Description	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date
1- 1	REPAIR SWINGLINE 270 ELECTRIC STAPLERS PROBLEM: WILL NOT STAPLE		4.00 EA	0.00	0.00	CLOSED
			Schedule Total		0.00	

Item Total

VENDOR IS DOING AN ADVANCE EXCHANGE. THE REPLACEMENT UNITS SHOULD BE HERE WITHIN 7-10 DAYS. ONCE THEY ARRIVE, THE DEPARTMENT HAS BEEN INSTRUCTED TO PUT THE DAMAGED UNITS INTO THE SAME BOXES AND PUT THE GREEN RETURN LABELS ON THE BOXES. ONCE THIS IS DONE THEY ARE TO CALL KRISTINA X7501 (IF I AM NO LONGER HERE, THEY SHOULD CALL STEVE X7014) SO THAT A RETURN CAN BE SET UP TO SEND BACK THE DAMAGED UNITS.

THE UNITS ARE IN ROOM 201 HCEB TO BE PICKED UP. BYU CONTACT: MELISSA PALMER (OR HILARY SMITH) X6047.

REPLACEMENTS HAVE BEEN RECEIVED. OLD UNITS TO BE SHIPPED BACK ON RA#2050. 5/26/99 KRW

Total PO Amount 0.00