Purchase Order

Brigham Young University BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

Supplier: 0000006346

CROWN AUDIO INC*DO NOT USE*

ATTN: SERVICE DEPT

PLANT: 2SW

1718 W MISHAWAKA RD ELKHART IN 46517 Dispatch via Print

0.00

Purchase Order		Date			Revision		Page	
BYU-0000036919		04,	/28/19	99	1 -	04/28	/1999	1
Payment Terms	Freight Ter	ms					Ship	Via
NET 30	FOB Orig	in,	Buyer	Ве	ars	Frt.	UPS	Ground
Buyer Whitney Kristina R			Phone/Email				Curr	ency

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exempt? Y Tax Exempt ID: N1002	0	Replenishment (
Line-Sch Item/Description	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date
1- 1 REPAIR CROWN GLM-200 MIC PRO NO AUDIO OUTPUT	DBLEM:	1.00EA	90.88	0.00	CLOSED
		Schedule Total	_	0.00	

Item Total

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING

SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

CHANGE ORDER #1

PUT PRICE INTO SYSTEM. CALLED VENDOR AFTER WE RECEIVED THE UNIT BACK TO FIND OUT THE PRICING. THEY SAID THAT THEY HAD ALREADY TALKED TO SOMEBODY (PROBABLY IN IT SERVICES) TO GET THE APPROVAL. 4/28/99 KRW