Purchase Order

Brigham Young University
BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 **United States**

Supplier: 0000012131

RESEARCH TECHNOLOGY INTERNATIONAL*

4700 CHASE

LINCOLNWOOD IL 60646-1689

Purchase Order Date Revision Page BYU-0000038361 08/18/1999 1 - 08/18/1999 Payment Terms **Freight Terms** Ship Via NET 30 FOB Origin, Buyer Bears Frt. UPS Ground **Buyer** Phone/Email Currency

Dispatch via Print

USD

0.00 CLOSED

Whitney, Kristina R RECEIVING Ship To:

1.00EA

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 **United States**

Attention: Not Specified

Bill To: **BRIGHAM YOUNG UNIVERSITY**

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exempt? Y Tax Exempt ID: N10020 Replenishment Option: Standard

Line-Sch Item/Description PO Price Mfa ID Quantity UOM Extended Amt Due Date

1- 1 REPAIR RTI VT2100 VIDEO INSPECTOR S/N: 160895 PROBLEM: VIDEO DRIVE

MOTORS NOT WORKING

Schedule Total 0.00

396.00

TAPE CLEANER BROKEN

Item Total 0.00

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING

SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

UNIT IS CURRENTLY BE WORKED ON. THE VENDOR IS TRYING TO PINPOINT THE PROBLEM. POSSIBLY WILL DONE NEXT WEEK SOMETIME??? 6/4/99 KRW

THREADING ARM WIRE CABLE SET \$16 VT POWER BOARD \$185 SERVICE LABOR 65/HR= \$195

PRICE CHANGED TO MATCH INVOICE. 8/18/99 KKN

Total PO Amount 0.00