Purchase Order

Brigham Young University
BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000000465 ELECTRO ACOUSTIC CO INC* 1610 BLOSSOM HILL RD STE 10 SAN JOSE CA 95124-6349

 Dispatch via Print

 Purchase Order
 Date
 Revision
 Page

 BYU-0000034393
 02/25/1999 1 - 02/25/1999 1
 02/25/1999 1
 1

 Payment Terms
 Ship Via
 NET 30
 FOB Origin, Buyer Bears Frt. UPS Ground

 Buyer
 Phone/Email
 Currency

USD

0.00

Whitney, Kristina R.

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exem	pt? Y Tax Exempt ID: N10020		Replenishment O	ption: Standard		
Line-Sch	Item/Description	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date
1- 1	REPAIR BELTONE 112 AUDIOMETER. PROBLEM: WON'T TRANSMIT A TONE		1.00EA	316.00	0.00	CLOSED
			Schedule Total		0.00	

Item Total

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

DAN BEASLEY OR ELECTRO ACOUSTICS CALLED WITH ESTIMATE. THEY CAN NOT FIX THE PROBLEM AND WILL HAVE TO SEND THE UNIT INTO BELL TONE FOR REPAIRS. APPOXIMATELY \$300 FOR REPAIRS, CALIBRATION. O.K. TO PAY PER MARK GHEEN OF IT SERVICES. HE ALSO REQUESTED THAT WE HAVE THE UNIT SHIPPED SECOND DAY BOTH WAYS. NOTIFIED DAN AT 408-445-3292. 2/11/99 KRW

CHANGE ORDER #1 REPAIRS COMPLETED. THE UNIT WAS SHIPPED DIRECTLY FROM THE FACTORY. THE FINAL COST IS \$316 PLUS SHIPPING. LABOR \$225 PARTS\$ 91, 2/25/99 KRW

Total PO Amount 0.00