Purchase Order

Brigham Young University BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000001624 SONY SERVICE CENTER HAVANA PLACE CENTER 10740 E ILIFF AVE AURORA CO 80014

Dispatch via Print **Purchase Order** Date Revision Page 08/25/1998 BYU-0000026065 Payment Terms **Freight Terms** Ship Via PAY NOW FOB Origin, Buyer Bears Frt. UPS Ground **Buyer** Phone/Email Currency USD

Whitney, Kristina R.

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exempt? Y Tax Exempt ID: N10020			Replenishment	Replenishment Option: Standard			
Line-Sch It	tem/Description	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date	
F	REPAIR SONY MDS-510 MINIC PLAYER. S/N 8826633 PROBI PHATTERS & CLICKS WHEN IT	EM:	1.00EA	161.95	0.00	CLOSED	
A NE\	// DISK, AND WHEN THE MACH	IINE IS FIRST TURNED "ON	Schedule Total	_	0.00		
ADVISE TH	E BUYER WHO SIGNED THIS C	ORDER OF REPAIR COST P	Item Total		0.00 ND IF UPS		

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING. SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED. PRE-PAY CHECK TO BE SENT SEPARATELY.

PER CHRISTIAN AT SONY SERVICE CENTER. 800-282-2848 THE WORK ORDER# IS W41E5205 AND IT IS IN FILE # E03309929. THE UNIT COULD NOT BE REPAIRED SO THEY ARE GOING TO SEND OUT AN EXCHANGE FOR IT. THE EXCHANGE UNIT HAS NOT YET COME IN. THEY WILL CALL WITH AN ESTIMATED TIME OF DELIVERY. 9/15/98 KRW

Total PO Amount	0.00