Purchase Order

Brigham Young University BRIGHAM YOUNG UNIVERSITY

PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

Supplier: 0000006346 CROWN AUDIO INC*DO NOT USE*

ATTN: SERVICE DEPT

PLANT: 2SW

1718 W MISHAWAKA RD **ELKHART IN 46517**

Dispatch via Print

Purchase Order	Date		Revi	Revision		Page	
BYU-0000026351	09	/24/199	981 -	09/24/	1998	1	
Payment Terms	Freight Terms				Ship	Via	
NET 30	FOB Origin,	Buyer	Bears	Frt.	UPS	Ground	
Buyer	uyer Phone/Email Currency						
Whitney.Kristina R. USD				-			

Ship To: RECEIVING

Attention: Not Specified

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 **United States**

BRIGHAM YOUNG UNIVERSITY FINANCIAL SERVICES Bill To:

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exem	pt? Y Tax Exempt ID: N1002	0	Replenishment	Option: Standa	rd	
Line-Sch	Item/Description	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date
1- 1	REPAIR CROWN LM200A MICROPHO 246590, PROBLEM: NO SOUND.	ONE SN:X	1.00EA	59.06	0.00	CLOSED
			Schedule Total	_	0.00	
			Item Total		0.00	

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

CHANGE ORDER#1 PRICE ADJUSTED TO REFLECT THE ESTIMATE GIVEN BY THE VENDOR. 9/24/98 KRW

lotal PO Amount	0.00