## **Purchase Order**

Brigham Young University BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000008763 TELEX COMMUNICATIONS INC WEST FIRST ST

WEST FIRST ST ATTN: SERVICE DEPT BLUE EARTH MN 56013 Dispatch via Print chase Order Date Revision Pag

Purchase Order	Dat	е	Revision	Р	age
BYU-0000027590	09/15/1998				1
Payment Terms	Freight Terms			Ship	Via
NET 30	FOB Origin,	Buyer	Bears Frt.	UPS	Ground
Buyer	Phone/Email			Curre	ency
Whitney, Kristina R.				USD	

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830

United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

**United States** 

 Tax Exempt?
 Y
 Tax Exempt ID:
 N10020
 Replenishment Option:
 Standard

 Line-Sch Item/Description
 Mfg ID
 Quantity UOM
 PO Price
 Extended Amt Due Date

1- 1 REPAIR RTS/TELEX MODEL BP-350 INTERCOM BELT PACK SN: B37077 1.00EA

0.00

0.00 CLOSED

**Schedule Total** 

0.00

PROBLEM: CHANNELS 1 & 2 COME THROUGH TOGETHER REGARDLESS OF SELECTOR SWITCH POSITION.

Item Total 0.00

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED. SPOKE WITH RACHEL IN REPAIRS. THE UNIT IS UNDER WARRANTY AND WILL BE SHIPPED ON 10/15/98. KRW

Total PO Amount 0.00