## **Purchase Order**

Brigham Young University
BRIGHAM YOUNG UNIVERSITY
PURCHASING DEPT
ASB C-40
PROVO UT 84602-1116 **United States** 

> Supplier: 0000000412 CRESTRON ELECTRONICS INC\* 15 VOLVO DR **ROCKLEIGH NJ 07647**

	Dispatch via Print					
Purchase Order	Dat	е	Revision	Page		
BYU-0000008020	08/29/1997			1		
Payment Terms	Freight Terms			Ship Via		
NET 30	FOB Origin,	Buyer	Bears Frt.	UPS Ground		
Buyer	Phone/Email			Currency		
Hullinger,Lisa	G.			USD		

llinger,Lisa G. **Ship To:** RECEIVING

Attention: Not Specified

**BRIGHAM YOUNG UNIVERSITY** CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830

**United States** 

BRIGHAM YOUNG UNIVERSITY FINANCIAL SERVICES Bill To:

A-153 ASB

PROVO UT 84602-1128
United States

		United States							
Tax Exempt? Y Tax Exempt ID	: N10020	Replenishment Option: Standard							
Line-Sch Item/Description	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date				
1- 1 REPAIR CRESTRON VS- ROUTING SWITCHER (ON		1.00EA	0.01	0.00	CLOSED				
		Schedule Total	_	0.00					
		Item Total	_	0.00					
CONFIRMING ORDER BY PHONE WITH CHARLIE DO NOT DUPLICATE RMA#28177 PROBLEM: DOESN'T SWITCH TO VCR OR SCREEN . (RBG SWITCHER) ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING									

**Total PO Amount** 0.00