## **Purchase Order**

Brigham Young University BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT

ASB C-40 PROVO UT 84602-1116 United States

Supplier: 0000016512

PANASONIC BROADCAST ENGINEERING CENTER

1713 N RANDALL RD DR 12

**ELGIN IL 60123** 

 Dispatch via Print

 Purchase Order
 Date
 Revision
 Page

 BYU-0000024809
 08/19/1998 2 - 08/19/1998 1

 Payment Terms
 Freight Terms
 Ship Via

 NET 30
 FOB Origin, Buyer Bears Frt.
 UPS Ground

Buyer Phone/Email Currency
Whitney,Kristina R. USD

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830

**United States** 

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

**United States** 

 Tax Exempt?
 Y
 Tax Exempt ID:
 N10020
 Replenishment Option:
 Standard

Line-Sch Item/Description Mfg ID Quantity UOM PO Price Extended Amt Due Date

1- 1 REPAIR PANASONIC AG-EZ1P CAMCORDER, SN: D6HY00045

1.00EA

276.51

0.00 CLOSED

**Schedule Total** 

0.00

PROBLEM: RECORD BUTTON NOT WORKING, NO SOUND, PLAY AS DIGITAL, COULD NOT DUPLICATE LAST ITEM.

Item Total

0.00

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED. INV#ME038893 FAX PAM 847-468-5275

**Total PO Amount** 

0.00