Purchase Order

Brigham Young University BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 **United States**

> Supplier: 0000014685 INTERWEST ELECTRONICS* 4091 S STATE SALT LAKE CITY UT 84107

Dispatch via Print

Purchase Order		Date		Revision		Page	
BYU-0000032905	0.2	/18/199	991 -	02/18/	1999	1	
Payment Terms	Freight Terms	;			Ship	Via	
NET 10	FOB Origin,	Buyer	Bears	Frt.	UPS	Ground	
Buyer	Phone/Email				Currency		
Whitney, Kristina R.				USD			

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 **United States**

Attention: Not Specified

BRIGHAM YOUNG UNIVERSITY FINANCIAL SERVICES Bill To:

A-153 ASB

PROVO UT 84602-1128

		United States							
Tax Exempt? Y Tax Exempt ID: N10020		Replenishment Option: Standard							
Line-Sch Item/Description	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date				
1- 1 REPAIR TOA A-912MK2 AMPLIFIER 7328266,	, sn:	1.00EA	123.30	0.00	CLOSED				
		Schedule Total		0.00					
PROBLEM: BRIDGE IN/OUT JACK DOESN'T WORK AND AMP REMAINS IN PROTECT MODE AFTER POWER-UP.									
		ltore Total		0.00					
		Item Total		0.00					
ADVISE THE BUYER WHO SIGNED THIS ORDE COURIER SERVICE. PLEASE CALL (801) 378-48			O BE PICKED UP	BY THE BYU					

CLAIM CHECK # 198331. VENDOR TO CALL IT SERVICES TO TALK ABOUT TECHNICAL STUFF AND GIVE THE ESTIMATE FOR REPAIR. CHANGED DUE DATE OUT TWO MORE WEEKS. 2/3/99 KRW

CHANGE ORDER #1 PRICE PUT INTO SYSTEM TO REFLECT ACTUAL COST PER VENDOR INVOICE. ESTIMATE HAD BEEN GIVEN TO MARK GHEEN. \$123.30 IS O.K. TO PAY PER MARK GHEEN OF IT SERVICES. 2/18/99 KRW

> **Total PO Amount** 0.00