## **Purchase Order**

Brigham Young University
BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 **United States** 

> Supplier: 0000001214 EIKI INTERNATIONAL INC PO BOX 514650 LOS ANGELES CA 90051-4650

Dispatch via Print **Purchase Order** Date Revision

Page BYU-0000034714 08/27/1999 2 - 08/27/1999 Freight Terms **Payment Terms** Ship Via NET 30 FOB Origin, Buyer Bears Frt. UPS Ground **Buyer** Phone/Email Currency USD Whitney,Kristina R

RECEIVING Ship To:

**BRIGHAM YOUNG UNIVERSITY** CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 **United States** 

Attention: Not Specified

Bill To: **BRIGHAM YOUNG UNIVERSITY** 

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

**United States** 

Tax Exempt? Y Tax Exempt ID: N10020 Replenishment Option: Standard PO Price Line-Sch Item/Description Mfa ID Quantity UOM Extended Amt Due Date

1- 1 REPAIR EIKI LC-5200 PROJECTOR S/N G5101232

1.00EA 1,590.00 0.00 CLOSED

Schedule Total

0.00

PROBLEM: CONTROL LED CAME ON, LAMP WILL NOT STRIKE UP. NEW LAMP DID NOT WORK AND LOW VOLTAGE SUPPLY AND LAMP SUPPLY WERE REPLACED.

**Item Total** 

0.00

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

ALISON TO CALL BACK BY 3/26 WITH AN ESTIMATE. 3/23/99 KRW

TECHS OUT SICK. HAVEN'T GOTTEN TO THIS UNIT YET. IT IS IN THE RUSH FILE. ALISON WITH CALL AS SOON AS SHE GETS THE ESTIMATE. 4/7/99 KRW

UNIT STILL AT VENDOR. IT IS WAITING FOR SOME PARTS. THE VENDOR DOES NOT KNOW HOW LONG IT WILL TAKE TO GET THE PARTS IN. ESTIMATE WAS GIVEN OF \$1608 TO INCLUDE A SIGNAL BOARD, MAIN BOARD, LINERS, AND LABOR. O.K. TO PAY PER STEVE ZOBELL OF ITSERVICES. 5/4/99 KRW

CHANGE ORDER #1

PUT ESTIMATE IN TO SYSTEM AS THE PRICE. THE PART THAT THEY ARE WAITING FOR SHOULD BE THERE IN 6 MORE WEEKS. 5/5/99 KRW

**CHANGE ORDER #2** 

PRICE CHANGED PER THAT OF LYNN AT EIKI. THIS SHOULD BE COMPLETE PRICE OF REPAIR. 8/26/99 KKN

**Total PO Amount** 

0.00