## **Purchase Order**

Brigham Young University
BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 **United States** 

Supplier: 0000017691

FOSTEX\*

ATTN: SERVICE DEPT 15431 BLACKBURN AVE NORWALK CA 90650

**Dispatch via Print** 

Purchase Order		Date		Re	Revision		Page	
BYU-0000030809		01,	/06/199	99 1	- 01/06	/1999	1	
Payment Terms	Freight Te	rms				Ship	Via	
NET 30	FOB Orig	in,	Buyer	Bear	s Frt.	UPS	Ground	
Buyer	Phone/Email				Currency			
Whitney Kristir					TICD	-		

RECEIVING Ship To:

**BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING** 685 E UNIVERSITY PKWY PROVO UT 84602-1830 **United States** 

Attention: Not Specified

Bill To: **BRIGHAM YOUNG UNIVERSITY** 

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

**United States** 

Tax Exempt? Y Tax Exempt ID: N10020 Replenishment Option: Standard Line-Sch Item/Description PO Price Mfg ID Quantity UOM Extended Amt Due Date

1- 1 REPAIR FOSTEX RD-8 TAPE RECORDER SER#0900782 PROB: THE SERVO DRIVE ON THE HEAD IS FAULTY

1.00EA 281.01 0.00 CLOSED

0.00

**Schedule Total** 

IT SEEMS TO SURGE AND PULSATE AS IT OPERATES. IT OCCASIONALLY GIVES A FAULT 5. THE ITEM HASN'T BEEN LOOKED AT YET. DUKE X123 WILL CALL ONCE IT GETS ON "THE TABLE". 12/21/98 KRW

> Item Total 0.00

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING. - KRISTINA WHITNEY 801-378-7501. SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED. FOR TECHNICAL QUESTIONS, CONTACT LYLE HILLIER OR MARK GHEEN AT 801-378-6713

CHANGE ORDER #1 PRICE ADDED TO SYSTEM PER ESTIMATE/INVOICE FROM VENDOR. \$281.01. 1/5/99 KRW

**Total PO Amount** 0.00