Purchase Order

Brigham Young University
BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 **United States**

> Supplier: 0000017743 TEAC AMERICA TASCAM ATTN: FACTORY SERVICE 7733 TELEGRAPH RD **MONTEBELLO CA 90640**

Dispatch via Print

Purchase Order		Dat	Date		Revision		Page	
BYU-0000036137		04	/02/199	99 1	_	04/01/	1999	1
Payment Terms	Freight Terms Ship Via							Via
NET 30	FOB Orig	in,	Buyer	Веа	rs	Frt.	UPS	Ground
Buyer	Pho	Phone/Email					Currency	
Whitney Kristir						HSD	-	

RECEIVING Ship To:

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 **United States**

Attention: Not Specified

Bill To: **BRIGHAM YOUNG UNIVERSITY**

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exempt? Y Tax Exempt ID: N10020 Replenishment Option: Standard PO Price Line-Sch Item/Description Mfa ID Quantity UOM Extended Amt Due Date

1- 1 REPAIR TASCAM CD-401 AUDIO CD PLAYER (SN 210116912)

1.00EA 194.56 0.00 CLOSED

Schedule Total

0.00

PROBLEM: IT SKIPS AND SOUNDS 'STATICY' AFTER PLAYING ABOUT 1/2-3/4 WAY THROUGH CD.

Item Total 0.00

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING

SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

CI AIM#216132 ACCT# 006678

SENT BACK IN 4/14/99 CLAIM# 216712

WARRANTY REPAIR.

CHANGE ORDER #1

PRICE PUT INTO SYSTEM TO REFLECT THE COST OF THE REPAIR PER LUPEY 323-727-7627. O.K. TO PAY PER MARK GHEEN OF ITSERVICES. 4/1/99 KRW

RECEIVED UNIT BACK ON 4/5/99. FAILED CHECK OUT. PROBLEM: COULD NOT PLAY 1ST TRACK ON 1ST 2 DISKS WITHOUT FAILING AND 3RD DISK COULD NOT BE RECOGNIZED. LEFT MESSAGE FOR LUPEY ABOUT PROBLEM. 4/6/99 **KRW**

> **Total PO Amount** 0.00