Purchase Order

Brigham Young University
BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 **United States**

> **Supplier:** 0000001214 EIKI INTERNATIONAL INC PO BOX 514650 LOS ANGELES CA 90051-4650

		Dispatch via Print				
Purchase Order	Date	e Revision	Page			
BYU-0000028156	09/	1				
Payment Terms	Freight Terms		Ship Via			
NET 30	FOB Origin,	Buyer Bears Frt	. UPS Ground			
Buyer		ne/Email	Currency			
Whitney, Kristin	USD					

Whitney,Kristina R. RECEIVING Ship To:

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 **United States**

Attention: Not Specified

Bill To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exem	npt? Y Tax Exempt ID: N10020	Replenishment Option: Standard					
Line-Sch	Item/Description	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date	
1- 1	REPAIR EIKI 7070 CASSETTE/CD PLAYER, SN: 07316, PROBLEM: CD PLAYER WON'T SPIN DISCS.		1.00EA	0.00	0.00	CLOSED	
			Schedule Total	_	0.00		
			Item Total		0.00		
SR# 29558 SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP							

FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED. ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING

ITEM TO SHIP BACK ON 11/6/98 PER DENISE. 11/5/98 KRW PER DENISE, THIS ITEM WAS UNDER WARRANTY AND THERE IS NO CHARGE, 11/12/98