Purchase Order

Brigham Young University
BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000010382 PHOTOMETRICS LIMITED* 3440 EAST BRITANNIA DRIVE TUCSON AZ 85706

Dispatch via Print **Purchase Order** Date Revision BYU-0000004763 10/16/1997 1 - 10/16/1997 Payment Terms **Freight Terms** Ship Via NET 30 FOB Origin, Buyer Bears Frt. Federal Express Economy Buyer Phone/Email Currency

USD

Hullinger, Lisa G.
Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

Bill To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exempt? Y Tax Exempt ID: N10020 Replenishment Option: Standard Quantity UOM Line-Sch Item/Description Mfg ID PO Price Extended Amt Due Date 1- 1 REPAIR OF CCD INVOLVING PARTS FROM 1.00EA 2,500.00 0.00 CLOSED THE FOLLOWING ICN #'S: **Schedule Total** 0.00 167878 (MODEL CH210), 156484 (MODEL CI181A), AND 156483 (MODEL CC200). RMA#: 6992 NOT TO EXCEED \$2500.00!! NOTE: ITEM NOT TO BE REPAIRED UNTIL MICHAEL JONER IS NOTIFIED OF THE ESTIMATES RECEIVED BY PURCHASING. Item Total 0.00 ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING. CONFIRMING ORDER BY PHONE

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING. CONFIRMING ORDER BY PHONE WITH ALLEN --- DO NOT DUPLICATE --- SHIP FEDERAL EXPRESS ECONOMY COLLECT. FOB ORIGIN. SHOW ACCOUNT # 165463056 AND PURCHASE ORDER # ON THE AIR BILL. THE USE OF ANY OTHER CARRIER OR SERVICE WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

Total PO Amount 0.00