Purchase Order

Brigham Young University
BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 **United States**

> **Supplier:** 0000001214 EIKI INTERNATIONAL INC PO BOX 514650 LOS ANGELES CA 90051-4650

Dispatch via Print Purchase Order Date Revision Page BYU-0000020321 05/21/1998 1 - 05/21/1998

Payment Terms **Freight Terms** Ship Via NET 30 UPS Ground FOB Origin, Buyer Bears Frt.

Buyer Phone/Email Currency

USD

0.00 CLOSED

0.00

Neitzel,Janae P Ship To:

RECEIVING **BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING** 685 E UNIVERSITY PKWY PROVO UT 84602-1830

United States

Attention: Not Specified

1.00EA

Schedule Total

Bill To: **BRIGHAM YOUNG UNIVERSITY**

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exempt? Y Tax Exempt ID: N10020 Replenishment Option: Standard Line-Sch Item/Description Quantity UOM PO Price Extended Amt Due Date Mfg ID

1- 1 REPAIR EIKI LC-5200 SN: G5101226. X PROBLEM: UNIT WILL SHUT DOWN COMPLETELY AFTER RUNNING

100.00

ANYWHERE FROM 6 HOURS TO 15 MINUTES. OVER TEMP LIGHT DOES NOT COME ON.

Item Total 0.00

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING

Total PO Amount 0.00