Purchase Order

Brigham Young University BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000017743 TEAC AMERICA TASCAM ATTN: FACTORY SERVICE 7733 TELEGRAPH RD MONTEBELLO CA 90640

	Dispatch via Print			
Purchase Order	Date	Revision	Page	
BYU-0000031483	12/02/1	998	_1	

Payment Terms Freight Terms Ship Via

NET 30 FOB Origin, Buyer Bears Frt. UPS Ground

Buyer Phone/Email Currency

USD

Whitney, Kristina R.

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exen	npt? Y Tax Exempt ID: N10020		Replenishment	Option: Standa	rd	
Line-Sch	Item/Description	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date
1- 1	REPAIR AUDIO CASSETTE TASCAM 424MK2 SN#7301368971 PROB: ASR. CAN'T GET THE TAPE IN OR OUT		1.00EA	0.00	0.00	CLOSED
			Schedule Total		0.00	

Item Total

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING SENT ACKNOWLEDGEMENT TO BYU PURCHASING ATTN:KRISTINA WHITNEY C-144 ASB PROVO, UT 84602. SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

T / 150 A	
Total PO Amount	0.00