Purchase Order

Brigham Young University BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000004398 GUITAR CITY 470 NORTH 1100 WEST CENTERVILLE UT 84014

Dispatch via Print

Purchase Order		Date	Revision	Page
BYU-0000027588		10/28/199	8 1 - 10/2	28/1998 1
Payment Terms	Freight Ter	ms		Ship Via
NET 10	FOB Origi	in, Buyer	Bears Frt	. UPS Ground
Buyer		Phone/Ema	Currency	
Whitney.Kristir	na R.			USD

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exempt? Y Tax Exempt ID: N10020		Replenishment Option: Standard				
Line-Sch Item/Description	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date	
1- 1 REPAIR FENDERS STAGE LEAD II GUITAR AMP SN: 201975, PROBLEM: AMP HAS HUMS	X	1.00EA	20.00	0.00	CLOSED	
		Schedule Total	_	0.00		
		Item Total		0.00		

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

TALKED TO KYLE AT GUITAR CITY. HE HAS SPOKEN WITH THE TECH AT M.S. THEY COULD NOT FIND THE PROBLEM. IF THE REPAIR PERSON DOESN'T FIND THE PROBLEM BY TODAY, THEY WILL SEND THE UNIT BACK. I FAXED AN ADDITIONAL COPY OF THE PO TO THEM. 10/9/98 KRW TO BE SHIPPED BACK TODAY. 10/21/98 KRW

CHANGE ORDER#1 PRICE ADJUSTED TO REFLECT THE DIAGNOSIS COST. NO REPAIR WORK WAS DONE. 10/28/98 KRW

Total PO Amount	0.0