Purchase Order

Brigham Young University BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000008324 PERFORMANCE AUDIO LLC 2456 S WEST TEMPLE SALT LAKE CITY UT 84115

 Dispatch via Print

 Purchase Order
 Date
 Revision
 Page

 BYU-0000035508
 03/18/1999 1 - 03/18/1999 1
 O3/18/1999 1
 Ship Via

 Payment Terms
 Freight Terms
 Ship Via

NET 10 F.O.B. Dest, Seller Bears Frt. BYU

Courier

Buyer Phone/Email Currency

Whitney, Kristina R. USD

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

 Tax Exempt?
 Y
 Tax Exempt ID:
 N10020
 Replenishment Option:
 Standard

 Line-Sch Item/Description
 Mfg ID
 Quantity UOM
 PO Price
 Extended Amt Due Date

1- 1 REPAIR OF QSC 3350 AMPLIFIER S/N:09549599

1.00EA 232.34

0.00 CLOSED

Schedule Total

0.00

PROBLEM: CHANNEL 1 DOESN'T COME OUT OF PROTECT MODE. END USERS ALSO SAYS IT "KEEPS BLOWING THE BREAKER IN THE AMP."

Item Total 0.00

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING TO BE PICKED UP BY THE BYU COURIER SERVICE. PLEASE CALL (801) 378-4835 WHEN MATERIAL IS READY FOR PICK-UP.

CHANGE ORDER #1

PRICE PUT INTO SYSTEM TO REFLECT ACTUAL COSTS OF REPAIR PER VENDOR. O.K. TO PAY PER MARK GHEEN OF ITSERVICES. 3/18/99 KRW

Total PO Amount 0.00