Purchase Order

Brigham Young University BRIGHAM YOUNG UNIVERSITY

PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 **United States**

> **Supplier:** 0000014738 PROTECH ELECTRONICS* 9486 S UNION SQUARE **SANDY UT 84070**

Dispatch via Print

Purchase Order		Date			Revision		Page			
BYU-0000028677		10,	/30/19	98	1 -	10/30/	1998	1		
Payment Terms	Freight Te	rms					Ship \	/ia		
NET 30	FOB Orig	in,	Buyer	Ве	ars	Frt.	Vendo	r's		
							Truck	2		
Buyer Phone/Email								Currency		
Whitney Kristina R							USD			

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 **United States**

Attention: Not Specified

BRIGHAM YOUNG UNIVERSITY FINANCIAL SERVICES Bill To:

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exem	npt? Y Tax Exempt ID: N1002	20	Replenishment	ard		
Line-Sch	Item/Description	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date
1- 1	REPAIR PIONEER LD-V8000 LAS S/N: 3910895 PROBLEM: DISK NOT SPIN		1.00EA	210.00	0.00	CLOSED
			Schedule Total	_	0.00	
			Item Total		0.00	

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING DAVE CALLED WITH ESTIMATE OF \$210 FOR PARTS AND LABOR TO REPLACE THE DISC SPIN MOTOR. WILL NEED TO ORDER NEW PART. APPROX 1-2 WEEKS. O.K. TO PAY PER STEVE ZOBELL. 10/9/98 KRW READY FOR PICK UP. COURIER TO DROP OFF ANOTHER UNIT AND PICK THIS ONE UP.

CHANGE ORDER #1 ADJUSTED PRICE TO REFLECT THE ESTIMATE GIVEN BY DAVE AT PROTECH. 10/30/98 KRW

Total PO Amount 0.00