Purchase Order

Brigham Young University BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000014738 PROTECH ELECTRONICS* 9486 S UNION SQUARE SANDY UT 84070

Dispatch via Print
ase Order Date Revision Pag

Purchase Order	Date	Revision	Page
BYU-0000039277	07/01/1999	2 - 03/27	2000 1
Payment Terms	Freight Terms		Ship Via
NET 30	FOB Origin, Buyer B	ears Frt.	BYU
			Courier
Buyer	Phone/Email		Currency
Whitney Kristir	na R.		USD

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

 Tax Exempt?
 Y
 Tax Exempt ID:
 N10020
 Replenishment Option:
 Standard

 Line-Sch Item/Description
 Mfg ID
 Quantity UOM
 PO Price
 Extended Amt
 Due Date

1- 1 REPAIR SONY SVO-9600 PROBLEM: WHEN THROUGHLY WARMED FINE RAINBOW LINES APPEAR ON SCREEN

1.00 EA **240.00**

0.00 CLOSED

Schedule Total

0.00

Item Total

0.00

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING

TO BE PICKED UP BY THE BYU COURIER SERVICE. PLEASE CALL (801) 378-4835 WHEN MATERIAL IS READY FOR PICK-UP.

(COURIER TO TAKE THE SERVICE MANUAL FROM IT SERVICES UP TO VENDOR. 6/1/99 KRW)

CHANGE ORDER 1

CALLED VENDOR 7/1/99 TO SEE STATUS ON REPAIR. VENDOR SAID HE WAS WAITING FOR APPROVAL ON THE QUOTE OF \$400-450 FROM HAROLD VAIL. I CALLED HAROLD WHO APPROVED THE ESTIMATE. VENDOR WAS NOTIFIED OF APPROVAL AND WE SHOULD RECEIVE THE ITEM 7/9 TO 7/14. KKN 7/1/99

CHANGE ORDER#2, CHANGED PRICE PER INVOICE PER ACCOUNTS PAYABLE. 3-27-00 RS

Total PO Amount 0.00