Purchase Order

Brigham Young University BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000014738 PROTECH ELECTRONICS* 9486 S UNION SQUARE SANDY UT 84070

 Purchase Order
 Date
 Revision
 Page

 BYU-0000031610
 12/15/1998
 2 - 12/15/1998
 1

 Payment Terms
 Freight Terms
 Ship Via

 NET 30
 FOB Origin, Buyer Bears Frt.
 BYU Courier

 Buyer
 Phone/Email
 Currency

USD

Whitney, Kristina R. **Ship To:** RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

Bill To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exempt? Y Tax Exempt ID: N10020			Replenishment Option: Standard			
Line-Sch Item/De	scription	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date
394180	REPAIR SONY CCDF 401 CAMCORDER SN: X 394180901, PROBLEM: LOAD MECHANISM JAMMED		1.00EA	125.00	0.00	CLOSED
			Schedule Total	_	0.00	
			Item Total		0.00	

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING TO BE PICKED UP BY THE BYU COURIER SERVICE. PLEASE CALL (801) 378-4835 WHEN MATERIAL IS READY FOR PICK-UP. (or call Kristina Whitney 801-378-7501)

CHANGE ORDER #1 REPAIR ESTIMATE GIVEN BY DAVE AT PROTECH OF \$120-\$130. THE DRIVE CIRCUIT NEEDS PARTS AND THE TAPE MECHANISMS NEEDS WORK. ESTIMATE APPROVED BY STEVE ZOBELL OF IT SERVICES. 12/11/98 KRW

CHANGE ORDER #2 PRICE ADJUSTED FROM \$130 TO \$125 WHICH WAS THE ACTUAL COST COMPARED TO THE ESTIMATE. 12/14/98 KRW

Total PO Amount	0.00