## **Purchase Order**

Brigham Young University
BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000008763 TELEX COMMUNICATIONS INC CUSTOMER SERVICE MANAGER 1720 E 14TH ST GLENCOE MN 55336

Purchase Order Date Revision Pag

BYU-0000028481 11/18/1998 1 - 11/18/1998 1

Payment Terms Freight Terms Ship Via

NET 30 FOB Origin, Buyer Bears Frt. UPS Ground

Buyer Phone/Email Currency
Whitney,Kristina R. USD

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

**United States** 

 Tax Exempt?
 Y
 Tax Exempt ID:
 N10020
 Replenishment Option:
 Standard

 Line-Sch Item/Description
 Mfg ID
 Quantity UOM
 PO Price
 Extended Amt
 Due Date

1- 1 REPAIR TELEX 6001 LCD PLATE, SN: X 10701, PROBLEM: WON'T COME ON

1.00 EA **134.50** 

0.00 CLOSED

Schedule Total

0.00

SENT WITH POWER SUPPLY

Item Total 0.00

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

CHANGE ORDER #1 PRICE ADJUSTED FROM \$0 TO \$134.50 PER VENDOR ESTIMATE FROM LANETTE 1-800-218-2410X212. O.K. TO PAY PER CHARLES EPPLEY. 11/17/98 KRW

Total PO Amount 0.00